

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

2005 NOV 25 AM 10:50

RECEIVED

070 FARMINGTON NM

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
Pride Energy Company

3a. Address
P.O. Box 701950, Tulsa, OK 74170

3b. Phone No. (include area code)
(918) 524-9200

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter B: 1,980' FEL and 660' FNL of Section 12-20N-3W

5. Lease Serial No.
NM 36096

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
San Isidro 12-2

9. API Well No.
30-043 -20721

10. Field and Pool, or Exploratory Area
Rio Puerco

11. County or Parish, State
Sandoval County, NM


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Drilled up CIBP @ 4,290'
 Cleaned out wellbore to PBTD @ 4503'
 Treat Gallup from 4115' to 4340' with 155 gals. of Xylene & 1500 gals. of 15% HCL

Put well to pumping on November 14, 2005.
 On November 16, 2005, produced 10 BO; 80 BW.
 Bond#: BD 101035



14. I hereby certify that the foregoing is true and correct
 Name (Printed/Typed) _____ Title _____
 Signature Matthew L. Pride Date 11/18/05
 By: Pride Production Co., Inc. Title: General Partner
 By: Matthew L. Pride Energy Company Title: President

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by _____ Title _____ Date _____
 Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.
 Office **ACCEPTED FOR RECORD**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NOV 29 2005
 FARMINGTON FIELD OFFICE

NMOCD