

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

XTO ENERGY INC.

3a. Address

2700 Farmington, Suite K-1, Farmington, NM 87401

3b. Phone No. (include area code)

505/324-1090

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1,740' FNL & 990' FWL Sec. 15, T26N, R11W

5. Lease Serial No.

NMM-03153

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Randel O.H. #9

9. API Well No.

30-045-26144

10. Field and Pool, or Exploratory Area

Gallegos Gallup

11. County or Parish, State

San Juan NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- | | | | |
|---|---|--|---|
| ☐ Acidize | ☐ Deepen | ☐ Production (Start/Resume) | ☐ Water Shut-Off |
| ☐ Alter Casing | ☐ Fracture Treat | ☐ Reclamation | ☐ Well Integrity |
| ☐ Casing Repair | ☐ New Construction | ☐ Recomplete | ☒ Other <u>PLUG</u> |
| ☐ Change Plans | ☐ Plug and Abandon | ☐ Temporarily Abandon | <u>BACK</u> |
| ☐ Convert to Injection | ☐ Plug Back | ☐ Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc plans to plug back this well from the Gallup formation to the Fruitland Coal per following steps:

- 1) MIRU PU.
- 2) CO to CIBP @ 5,291'. ~~Dump ball 50'~~ cmt on top of CIBP. to 5162' (Gallup top @ 5212')
- 3) Spot 100' cmt plug across the Cliff House formation fr/3,126' - 3,226'. 2600' - 2500' + 50' x-ray
- 4) Run GR/CCL/CBL log from 2,100' - 305.
- 5) Set CIBP @ 1,900'. Perf Fruitland coal from 1,637' - 1,669'. Frac Fruitland Coal with 20# XL gel carrying 115,000# 20/40 Brady sd.
- 6) CO sand to CIBP at 1,900'.
- 7) Install rod pumping equipment.
- 8) RDMO PU.



14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

HOLLY C. PERKINS

REGULATORY COMPLIANCE TECH

Date 11/2/2005

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

NOV 14 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD