UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CHAIDDY	MOTICES	AND	REPORTS	ANI	WELLE
SHNDRA	NOTICES	ANL	REPURIS	ON	WELLS

FORM APPROVED
OMB No. 1004-0137 Expires: March 31, 2007
Expires: March 31, 2007

Lease	Serial	No.	

	NOTICES AND REF		/	SF-0/93	
Do not use th abandoned we	nis form for proposals t ell. Use Form 3160-3 (/	to drill or to re- APD) for such p	enter an 23 roposais, LB 23	سم ا	, Allottee or Tribe Name
	IPLICATE- Other instr		orse side. REC		r CA/Agreement, Name and/or No.
Type of Well Oil Well	Gas Well Other	•	UTO FARM	MGTOM 8. Well Na	5P35-85C-410 me and No.
Name of Operator NM&O Oper	rating Company			#3 Ruc	ker Lake ell No.
. Address 15 East 5 th, STE 3000		3b. Phone No. (inclu 918 584-3802	de area code)		232240051 ad Pool, or Exploratory Area
Location of Well (Footage, Sec.,	T., R., M., or Survey Description)			-	n Mancos
1760' FSL & 940' FWL Sec 25, T25N, R2W					or Parish, State
12. CHECK AJ	PPROPRIATE BOX(ES) TO	INDICATE NATU	TRE OF NOTICE, R	EPORT, OF	R OTHER DATA
TYPE OF SUBMISSION		T	YPE OF ACTION		
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (St	art/Resume)	Water Shut-Off Well Integrity Other Status Report
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back			
If the proposal is to deepen dire Attach the Bond under which the following completion of the in- testing has been completed. Find determined that the site is read. Move well service unit to	ectionally or recomplete horizontal the work will be performed or provivolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) well location on or about Febr	lly, give subsurface locar vide the Bond No. on file in results in a multiple con e filed only after all requi ruary 25, 2006 to con	ions and measured and tre with BLM/BIA. Requir impletion or recompletion rements, including reclan imence well workover	ed subsequent in a new interv- nation, have be- operations.	hs of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has Plans are to set a CIBP at 6750',
Attach the Bond under which the following completion of the intesting has been completed. Findetermined that the site is read Move well service unit to approximately 50' above the following statement of the statement of the following sta	ectionally or recomplete horizontal the work will be performed or provivolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) well location on or about Febr	lly, give subsurface local vide the Bond No. on file in results in a multiple con e filed only after all requi- ruary 25, 2006 to con perforations, then do	ions and measured and tree with BLM/BIA. Requirempletion or recompletion rements, including reclanamence well workover imp 25' of cement on the	ed subsequent in a new interv- nation, have be- operations.	hs of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has
If the proposal is to deepen dire Attach the Bond under which the following completion of the intesting has been completed. Find determined that the site is ready Move well service unit to approximately 50' above to 5633'-38' and 5670'-5695'	ectionally or recomplete horizontal the work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be ty for final inspection.) well location on or about Febr the current Gallup formation will then be perforated, and a	lly, give subsurface local vide the Bond No. on file in results in a multiple con e filed only after all requi- ruary 25, 2006 to con perforations, then do	ions and measured and tree with BLM/BIA. Requirempletion or recompletion rements, including reclanamence well workover imp 25' of cement on the	ed subsequent in a new interv- nation, have be- operations.	ths of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has clams are to set a CIBP at 6750', The Mesa Verda zone intervals
If the proposal is to deepen dire Attach the Bond under which it following completion of the intesting has been completed. Fi determined that the site is ready Move well service unit to approximately 50' above to 5633'-38' and 5670'-5695'	ectionally or recomplete horizontal the work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be ty for final inspection.) well location on or about Febr the current Gallup formation will then be perforated, and a	lly, give subsurface local vide the Bond No. on file in results in a multiple con e filed only after all requi- ruary 25, 2006 to con perforations, then do	ions and measured and tree with BLM/BIA. Requirempletion or recompletion rements, including reclanamence well workover imp 25' of cement on the	ed subsequent in a new intervaluation, have been operations. op of CIBP.	ths of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has clams are to set a CIBP at 6750', The Mesa Verda zone intervals
If the proposal is to deepen dire Attach the Bond under which it following completion of the intesting has been completed. Fi determined that the site is ready Move well service unit to approximately 50' above to 5633'-38' and 5670'-5695'	ectionally or recomplete horizontal the work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be ty for final inspection.) well location on or about Febr the current Gallup formation will then be perforated, and a	lly, give subsurface local ride the Bond No. on file in results in a multiple core filed only after all requirements 25, 2006 to conperforations, then dead dized and fracture	ions and measured and tree with BLM/BIA. Requirempletion or recompletion rements, including reclanamence well workover imp 25' of cement on the	ed subsequent in a new intervi- nation, have be- operations.	hs of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has Plans are to set a CIBP at 6750', The Mesa Verda zone intervals
If the proposal is to deepen dire Attach the Bond under which the following completion of the int testing has been completed. Fit determined that the site is ready Move well service unit to approximately 50' above to 5633'-38' and 5670'-5695' 14. I hereby certify that the fore Name (Printed/Typed)	ectionally or recomplete horizontal the work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be ty for final inspection.) well location on or about Febr the current Gallup formation will then be perforated, and a	lly, give subsurface local ride the Bond No. on file in results in a multiple core filed only after all requirements 25, 2006 to conperforations, then dead dized and fracture	ions and measured and tre with BLM/BIA. Requirements or recompletion rements, including reclaramence well workover imp 25' of cement on the treated.	and Control	hs of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has Plans are to set a CIBP at 6750', The Mesa Verda zone intervals
If the proposal is to deepen dire Attach the Bond under which the following completion of the intesting has been completed. Find tetermined that the site is ready Move well service unit to approximately 50' above to 5633'-38' and 5670'-5695' 14. Thereby certify that the fore Name (Printed/Typed) Scott Behm	ectionally or recomplete horizontal the work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be ty for final inspection.) well location on or about Febr the current Gallup formation will then be perforated, and a	lly, give subsurface local ride the Bond No. on file in results in a multiple core filed only after all requirements of the comperforations, then deactdized and fracture the core filed only after all requirements.	ions and measured and tree with BLM/BIA. Requirempletion or recompletion rements, including reclarations are well workover imp 25' of cement on the treated. Operations Analysis	and Control	hs of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has Plans are to set a CIBP at 6750', The Mesa Verda zone intervals
If the proposal is to deepen dire Attach the Bond under which the following completion of the intesting has been completed. Findetermined that the site is ready Move well service unit to approximately 50' above to 5633'-38' and 5670'-5695' 14. Thereby certify that the fore Name (Printed/Typed) Scott Behm	ectionally or recomplete horizontal the work will be performed or prov volved operations. If the operation inal Abandonment Notices shall be ty for final inspection.) well location on or about Febr the current Gallup formation will then be perforated, and a	lly, give subsurface local ride the Bond No. on file in results in a multiple core filed only after all requirements of the comperforations, then deactdized and fracture the core filed only after all requirements.	ions and measured and tree with BLM/BIA. Requirempletion or recompletion rements, including reclarations are well workover imp 25' of cement on the treated. Operations Analysis	and Control	hs of all pertinent markers and zones. reports shall be filed within 30 days al, a Form 3160-4 shall be filed once en completed, and the operator has Plans are to set a CIBP at 6750', The Mesa Verda zone intervals

(Instructions on page 2)