Form 3160-5 (August 2007)       UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT         SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.         SUBMIT IN TRIPLICATE - Other instructions on reverse side.         1. Type of Well         Oil Well       Gas Well				None	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM03526		
					6. If Indian, Allottee or Tribe Name         EASTERN NAVAJO         7. If Unit or CA/Agreement, Name and/or No.         892000844E         8. Well Name and No.         GALLEGOS CANYON UNIT 510		
				5			
2. Name of Operator BP AMERICA PRODUCTION CO E-Mail: Toya.Colvin@bp.com					9. API Well No. 30-045-28311-00-C1		
3a. Address3b. Phone No200 ENERGY COURTPh: 281-36FARMINGTON, NM 87401Ph: 281-36			(include area code) -7148 PINON FRUITLAND SAND NC		ED CLIFFS WEST		
4. Location of Well (Footage, Sec., 7	11. County or Parish, and State						
Sec 28 T29N R12W NWNE 1075FNL 1655FEL 36.701860 N Lat, 108.100680 W Lon					SAN JUAN COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	<ul> <li>Acidize</li> <li>Alter Casing</li> </ul>	Deej Frac	oen ture Treat	<ul> <li>Production (Start/Resume)</li> <li>Reclamation</li> </ul>		□ Water Shut-Off □ Well Integrity	
□ Subsequent Report	Casing Repair	□ New	Construction	Recomplete		□ Other	
Final Abandonment Notice			Tempora	porarily Abandon			
3. Describe Proposed or Completed Op	Convert to Injection	D Plug	Service and the service of the	U Water Di			
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Ai determined that the site is ready for f BP America Production Comp	rk will be performed or provide th d operations. If the operation resu bandonment Notices shall be filed inal inspection.) pany respectfully requests F	ne Bond No. on Its in a multiple I only after all r P&A the subj	file with BLM/BL e completion or rec equirements, inclu-	A. Required subs completion in a ne	sequent reports shall be w interval, a Form 310 have been completed,	filed within 30 days 50-4 shall be filed once	
Please see the attached procedure including wellbore diagrams. In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop				vstem during	em during OCT <b>21</b> 2015		
ACTION DOES NOT OPERATOR FROM	DR ACCEPTANCE OF THIS RELIEVE THE LESSEE AN OBTAINING ANY OTHER EQUIRED FOR OPERATIO INDIAN LANDS	prior t	MOCD 24 hrs o beginning erations		E ATTACHE	D FOR	
<ul> <li>14. I hereby certify that the foregoing is</li> <li>Co</li> <li>Name (Printed/Typed) TOYA CO</li> </ul>	Electronic Submission #31 For BP AMERICA I mmitted to AFMSS for proce	PRODUCTIO	N CO, sent to th CK SAVAGE on	e Farmington	JWS0007SE)		
Signature (Electronic			Date 10/08/2		F	and the second sec	
	THIS SPACE FOR	TEDERA	LUKSIAIE	OFFICE US			
Approved By JACK SAVAGE					Date 10/16/20		
ertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Farmington				
men would entitle the appheant to cond							

.

R

\*\* BLM REVISED \*\*

NMOCDAY

6

## September 11, 2015

## NMOCD

BP would like to permanently abandon the **Gallegos Canyon Unit # 510** well, as per the proposed procedure and wellbore sketches.

West Kutz Pictured Cliffs / Pinon Fruitland Sand North 1057' FNL and 1655' FEL, Section 28, T29N, R12W San Juan County, New Mexico / API 30-045-28311 Lat: / Lat:

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
  - 1. This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
  - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
  - 3. Rods: Yes \_\_\_\_\_, No \_\_\_\_, Unknown \_\_\_\_\_.

     Tubing: Yes X \_\_\_\_\_, No \_\_\_\_\_, Unknown \_\_\_\_\_, Size \_\_\_\_\_.

     Packer: Yes \_\_\_\_\_\_, No X \_\_\_\_\_, Unknown \_\_\_\_\_\_, Type \_\_\_\_\_\_.

     If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
  - 4. Plug #1 (Pictured Cliffs interval, 1267- 1167'): Round trip gauge ring or mill to 1267' or as deep as possible. PU and TIH with 4.5" cement retainer, set at 1267'. Pressure test tubing to 1000 PSI. Mix and pump 16 sxs Class B cement above CR to isolate the Pictured Cliffs interval. PUH and WOC. TIH and tag cement. If necessary top off cement.
  - 4. Plug #2 (Fruitland Sands interval, 1006' 906'): PU and TIH with 4.5" cement retainer, set at 1006'. Pressure test tubing to 1000 PSI. *Pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plug as appropriate.* Mix and pump 12 sxs Class B cement above CR to isolate the Fruitland Sands interval. PUH.
  - 5. Plug #3 (Kirtland top and Surface Casing shoe, 190' to Surface): Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix

approximately 15 sxs Class B cement and spot a balanced plug inside the casing from 190' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then <u>perforate at the appropriate depth</u> and attempt to circulate cement to surface filling the 4.5" casing and the BH annulus to surface. Shut well in and WOC.

 ND BOP and cut off wellhead below surface casing flange. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations.



TD 1415' PBTD 1363'

## Gallegos Canyon Unit #510 Proposed P&A

West Kutz Pictured Cliffs / Pinon Fruitland Sand North 1057' FNL, 1655' FEL, Section 28, T-29-N, R-12-W, San Juan County, NM / API #30-045-28311 Lat \_\_\_\_\_ / Long \_\_\_\_\_

TOC @ Surface, circulated 15 bbls To surface per sundry

7" 20#, K-55 Casing set @ 136' Cement with 120 sxs (Circulated to Surface)

> Plug #3: 190' – 0' Class B cement, 15 sxs

Plug #2: 1006' – 906' Class B cement, 12 sxs

Set CR @ 1006'

Fruitland Sand Perforations: 1056' - 1080'

Plug #1: 1267' – 1167' Class B cement, 16 sxs (excess due to open perfs)

Set CR @ 1267'

Pictured Cliffs Perforations: 1317' – 1350'

4.5",10.5#, J-55 Casing set @ 1451' Cement with 250 sxs Circulate cement to surface

Today's Date: **9/11/15** Spud: 1/22/91 PC Completed 3/6/91 FS Completed 2/18/03 Elevation: 5363' GI 5373' KB

8-3/4" hole



Fruitland @ 1006'

Pictured Cliffs @ 1318'

6.25" hole



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Gallegos Canyon Unit #510

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.