RECEIVED

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

als.					
	7. If Unit of CA/Agreement, Name and/or No. San Juan 30-6 Unit 8. Well Name and No. San Juan 30-6 Unit 414S				
	9. API Well No. 30-039-27305				
ode) O	10. Field and Pool or Exploratory Area Basin Fruitland Coal				
R7W	11. Country or Parish, State Rio Arriba , New Mexico				

Bureau of Landon arotous				SF-079383	
Bureau of Landon arotous	DRY NOTICES AND REPO	ORTS ON WELLS	6. If Indian, Allottee	Decretor de la contraction de	
abandoned	ethis form for proposals				
	well. Use Form 3160-3 (A	(PD) for such propose	als.		
SI	UBMIT IN TRIPLICATE - Other ins	structions on page 2.	7. If Unit of CA/Ag	reement, Name and/or No.	
1. Type of Well			San Juan 30-6 Unit		
Oil Well	X Gas Well Other		8. Well Name and N	No.	
				an Juan 30-6 Unit 414S	
2. Name of Operator			9. API Well No.	00 000 07007	
	gton Resources Oil & Gas	3b. Phone No. (include area co	de) 10 Field and Paul	30-039-27305	
3a. Address PO Box 4289, Farmingt	ton NM 87499	(505) 326-9700		10. Field and Pool or Exploratory Area Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T., I		(505) 520-5700	11. Country or Paris		
	WNW), 1600' FNL & 1225' I	FWL. Sec. 35, T30N, R		The second secon	
5,11,2 (6.	, 1000 1 112 0 1220 1	,,		, non money	
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE, REPORT	OR OTHER DATA	
	1				
TYPE OF SUBMISSION		TYPE	OF ACTION		
X Notice of Intent	Acidize	Deepen	Production (Start/Resu	ime) Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	X Other TA Sta	itus
	Change Plans	Plug and Abandon	X Temporarily Abandon	Extensi	ion
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
			last MIT was perform	-	ect
Notify NMOCD 24 hrs prior to beginning operations	OPERA AUTHO	TOR FROM OBTAINING			
op or management	01.12	DERAL AND INDIAN LAN	OR OPERATIONS		
		DERAL AND INDIAN LAN	OR OPERATIONS	OIL CONS. DIV DIST	. 3
TA approved	antil 11/2/-	DERAL AND INDIAN LAN	OR OPERATIONS	OIL CONS. DIV DIST. OCT 2 7 2015	. 3
	antil 11/2/-	DERAL AND INDIAN LAN	OR OPERATIONS		. 3
14. I hereby certify that the foregoing is	antil 11/2/-	2016	FOR OPERATIONS		. 3
14. I hereby certify that the foregoing is Dollie L. Busse	antil 11/2/-	2016 Title Staff R	Regulatory Technician		. 3
14. I hereby certify that the foregoing is	true and correct. Name (Printed Type)	2016 Title Staff R	Regulatory Technician		. 3
14. I hereby certify that the foregoing is Dollie L. Busse	true and correct. Name (Printed Type)	2016 Title Staff R	Regulatory Technician		. 3
TA approved	antil 11/2/-	DERAL AND INDIAN LAN	OR OPERATIONS		. 3

Conditions of approval if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ConocoPhillips SAN JUAN 30-6 UNIT 414S Expense - MIT

Lat 36° 46' 18.948" N

Long 107° 32' 40.344" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM and COPC safety and environmental regulations. Notify regulatory, BLM and NMOCD at least 7 days prior to planned MIT.
- 2. MIRU pump truck. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Wells Engineer.
- 3. Blow down casing pressure if necessary.
- 4. Load casing with 2 % KCl water & corrosion inhibitor, as necessary. Perform MIT (Mechanical Integrity Test) above the bridge plug at 3,350' to 560 psig for 30 minutes on a 2 hour chart with 1000 lb. spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.

