

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010

RECEIVED  
NOV 03 2015  
Bureau of Land Management  
Farmington Field Office

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

SUBMIT IN TRIPLICATE - Other instructions on page 2.

|   |  |   |
|---|--|---|
| 1. Type of Well<br><input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other              |  | 5. Lease Serial No.<br><b>SF-079729</b>                                       |
| 2. Name of Operator<br><b>Burlington Resources Oil &amp; Gas Company LP</b>   |  | 6. If Indian, Allottee or Tribe Name  |
| 3a. Address<br><b>PO Box 4289, Farmington, NM 87499</b>   | 3b. Phone No. (include area code)<br><b>(505) 326-9700</b> | 7. If Unit of CA/Agreement, Name and/or No.<br><b>San Juan 28-4 Unit</b>      |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)<br><b>Unit K (NESW), 2030' FSL &amp; 1570' FWL, Sec. 17, T28N, R4W</b> |  | 8. Well Name and No.<br><b>San Juan 28-4 Unit NP 226</b>                      |
|   |  | 9. API Well No.<br><b>30-039-25286</b>  |
|   |  | 10. Field and Pool or Exploratory Area<br><b>Basin FC / Chosa Mesa PC Ext</b> |
|   |  | 11. Country or Parish, State<br><b>Rio Arriba, New Mexico</b>                 |

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                |   |  |  |
|---|---|---|--|--|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off                    |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity                    |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                | <input checked="" type="checkbox"/> Other <b>BH Repair</b> |
|   | <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |  |
|   | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            |  |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

10/22/15 MIRU KEY 6091. ND WH. NU BOPE. PT BOPE. Test - Failed. RIH w/ pkr @ 30'. PT to 600#. Test - Failed. POOH w/ pkr. RIH w/ RBP set @ 60'. Set pkr @ 30'. PT RBP to 500#. Test - OK. POOH w/ Pkr. NU BOPE & tbg head. Test seals 2/ hand pump to 2000#. Test - OK. NU & Test BOPE w/ RBP @ 60' to 500#. Test - Failed. Set pkr @ 16' & 3'. Test Failed. ND BOPE. Identified two holes in 4 1/2" csg @ 2' below surface. NU BOPE. POOH w/ tbg. 10/24/15 Set pkr @ 4115'. Test to 600#. Test-Failed. Release Pkr. Tag RBP. Test - Failed. Release Pkr & Circ hole. Set Pkr & PT. Test - Failed. Release Pkr. Set Pkr @ 30'. PT to 600#/15min. Test - OK. RU W/L. Run CBL from 4123' to Surface. RD W/L. 10/27/15 Spear into 4 1/2" csg. Cut off WH. Cut 4 1/2" csg with hole & remove. Weld new 4 1/2" stump & WH. NU tbg head. Test seals to 3000# w/ hand pump. Test - OK. PT WH & csg from Surface to 4127' to 530#/30min. Test - OK. 10/28/15 RIH w/ 139jts 2 3/8", 4.7#, J-55 tbg set @ 4450' w/ F-Nipple @ 4448'. ND BOPE. NU WH. RD RR @ 16:30hrs on 10/28/15.

OIL CONS. DIV DIST. 3

NOV 09 2015

ACCEPTED FOR RECORD

NOV 03 2015

|  |  |  |  |
|--|--|--|--|
| 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)<br><b>Crystal Walker</b> |  | Title<br><b>Regulatory Coordinator</b> |  |
| Signature<br><i>Crystal Walker</i>   |  | Date<br><b>11/2/2015</b>               |  |

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

|   |        |      |
|---|--------|------|
| Approved by   | Title  | Date |
| Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. | Office |      |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.