

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

JAN 08 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Burlington Resources Oil & Gas Co.	Contact Bobby Spearman
Address 3401 East 30th St, Farmington, NM	Telephone No. (505)-320-3045
Facility Name: Allison 1R	Facility Type: Gas well

Surface Owner: Fee	Mineral Owner: Fee	API No. 30045289570000
---------------------------	---------------------------	-------------------------------

LOCATION OF RELEASE

Unit Letter E	Section 17	Township 32N	Range 6W	Feet from the 1915	North/South Line North	Feet from the 655	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

**Latitude _Longitude
NATURE OF RELEASE**

Type of Release Produced water	Volume of Release 97bbls	Volume Recovered 50bbls
Source of Release Produced water tank	Date and Hour of Occurrence 12-30-15 8:00a	Date and Hour of Discovery 12-30-15 8:00a
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith NMOCD	
By Whom? Lisa Hunter	Date and Hour 12-30-15 @2:30p	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole in the burner tube caused at release 97bbls of produced water. 50bbls of fluid was recovered. The release was contained within the berm and did not leave location. The landowner has been notified. When weather permits, the affected soil will be sampled to determine further remediation

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bobby Spearman	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 1/21/2016	Expiration Date:
E-mail Address: Robert.E.Spearman@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/4/2016	Phone: (505) 320-3045	

* Attach Additional Sheets If Necessary

*Sample TPH, BTEX, Chlorides
NCS 15364543*

①