OIL CONS. DIV DIST. 3

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NOV 03 2015

Reclamation

Recomplete

Temporarily

Abandon

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

Well Integrity

COMPLETION

Other

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name

Sase Serial No.

abandoned well.	Use Form 3160-3 ((APD) for such proposals ington F	ield Office	
SUBMIT IN TRIPLICATE - Other instructions on page Qureau of Land				
1. Type of Well			134816	
			8. Well Name and No.	
Oil Well Gas Well Other			MC 5 COM #119H	
Name of Operator WPX Energy Production, LLC			9. API Well No. 30-045-35601	
3a. Address PO Box 640 Aztec, NM	87410	3b. Phone No. (include area code) 505-333-1816	10. Field and Pool or Exploratory Area Basin mc	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL:1290' FNL & 388' FWL, sec 33, T24N, R8W BHL:332' FSL & 1294' FWL, sec 34, T24N, R8W		11. Country or Parish, State San Juan, NM		
12. CHECK	THE APPROPRIATE BOX	(ES) TO INDICATE NATURE OF NOTICE, R	EPORT OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen Produ (Start/Resi	uction Water Shut-Off	

Final Abandonment Notice Plug Back Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Fracture Treat

New Construction

Plug and Abandon

9/24/15- MIRU

Subsequent Report

RIH to to 800', run csg integrity log to surface, checked out good, RIH to 4500', run csg integrity and wall thickness log to surface, tight spot of 6.2" ID at 3800', continue to surface, recalibrate logging tool, RIH to 4500' again and log to surface, csg looked better

9/25/15- MIRU Baker Hughes hard lines, prsr test lines to 9500 psi, tested good w/ no leak off, RU Antelope prsr test unit, load well w/ Baker, increase prsr to 5800 psi, monitor and chart for 30 min, tested good w/ no leak off.

9/26/15-9/28/15- Prepare for frac

14. I hereby certify that the foregoing is true and correct.

9/29/15-Perf MANCOS 1st stage, 13277'-13461' + RSI TOOL @ 13466' with 18, 0.40" holes. RD.

Alter Casing

Casing Repair

Change Plans

LACEY GRANILLO	Title PERMITTING TECH III Date 10/29/15		OCT 3 0 2015
THIS SPACE FOR FEDERAL OR STA	TE OFFICE	USE	
Approved by	Title	Date	FARMING ON FIELD OFFICE BY:
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office		Province Service

(Instructions on page 2)



9/30/15-Frac MANCOS 1st stage 13277'-13466'- with 214,319# 20/40 PSA Sand

Set flo-thru frac plug @ 13254' MD. Perf 2nd stage 13031'-13215'-with 24, 0.40" holes. Frac MANCOS 2nd stage with 215,623#, 20/40 PSA Sand Set flo-thru frac plug @ 13001' MD. Perf 3rd stage 12785'-13971'- with 24, 0.40" holes. Frac MANCOS 3rd stage with 214,750#, 20/40 PSA Sand 10/1/15-Set flo-thru frac plug @ 12750' MD. Perf 4th stage 12539'-12727'- with 24, 0.40" holes. Frac MANCOS 4th stage with 201,075#, 20/40 PSA Sand Set flo-thru frac plug @ 12514' MD. Perf 5th stage 12323'-12477'-with 24, 0.40" holes. Frac MANCOS 5th stage with 217,692#, 20/40 PSA Sand Set flo-thru frac plug @ 12300' MD. Perf 6th stage 12117'-12271'- with 24, 0.40" holes. Frac MANCOS 6th stage with 214,431#, 20/40 PSA Sand Set flo-thru frac plug @ 12092' MD. Perf 7th stage 11911'-12069'- with 24, 0.40" holes. Frac MANCOS 7th stage with 214,726#, 20/40 PSA Sand Set flo-thru frac plug @ 11880' MD. Perf 8th stage 11705'-11861'- with 24, 0.40" holes. Frac MANCOS 8th stage with 214,729#, 20/40 PSA Sand 10/2/15-Set flo-thru frac plug @ 11680' MD. Perf 9th stage 11499'-11651'- with 24, 0.40" holes. Frac MANCOS 9th stage with 214,756#, 20/40 PSA Sand Set flo-thru frac plug @ 11470' MD. Perf 10th stage 11293'-11447'- with 24, 0.40" holes. Frac MANCOS 10th stage with 214,352#, 20/40 PSA Sand Set flo-thru frac plug @ 11270' MD. Perf 11th stage 11090'-11241'- with 24, 0.40" holes. Frac MANCOS 11th stage with 214,671#, 20/40 PSA Sand Set flo-thru frac plug @ 11062' MD. Perf 12th stage 10881'-11035'- with 24, 0.40" holes. Frac MANCOS 12th stage with 214,984#, 20/40 PSA Sand Set flo-thru frac plug @ 10856' MD. Perf 13th stage 10675'-10831'- with 24, 0.40" holes. Frac MANCOS 13th stage with 207,848#, 20/40 PSA Sand 10/3/15-Set flo-thru frac plug @ 10644' MD. Perf 14th stage 10469'-10625'- with 24, 0.40" holes. Frac MANCOS 14th stage with 215,832#, 20/40 PSA Sand Set flo-thru frac plug @ 10450' MD. Perf 15th stage 10263'-10417'- with 24, 0.40" holes. Frac MANCOS 15th stage with 214,375#, 20/40 PSA Sand Set flo-thru frac plug @ 10240' MD. Perf 16th stage 10057'-10211'- with 24, 0.40" holes. Frac MANCOS 16th stage with 214,067#, 20/40 PSA Sand Set flo-thru frac plug @ 10030' MD. Perf 17th stage 9851'-10010'- with 24, 0.40" holes. Frac MANCOS 17th stage with 213,486#, 20/40 PSA Sand Set flo-thru frac plug @ 9820' MD. Perf 18th stage 9645'-9801'- with 24, 0.40" holes. Frac MANCOS 18th stage with 212,333#, 20/40 PSA Sand Set flo-thru frac plug @ 9625' MD. Perf 19th stage 9439'-9595'- with 24, 0.40" holes. Frac MANCOS 19th stage with 215,971#, 20/40 PSA Sand 10/4/15-Set flo-thru frac plug @ 9415' MD. Perf 20th stage 9233'-9380'- with 24, 0.40" holes. Frac MANCOS 20th stage with 214,784#, 20/40 PSA Sand Set flo-thru frac plug @ 9220' MD. Perf 21st stage 9027'-9181'- with 24, 0.40" holes. Frac MANCOS 21st stage with 214,575#, 20/40 PSA Sand Set flo-thru frac plug @ 9000' MD. Perf 22nd stage 8821'-8975'- with 24, 0.40" holes. Frac MANCOS 22nd stage with 215,995#, 20/40 PSA Sand Set flo-thru frac plug @ 8800' MD. Perf 23rd stage 8615'-8769'- with 24, 0.40" holes. Frac MANCOS 23rd stage with 214,163#, 20/40 PSA Sand 10/5/15-10/13/15- wait on other frac

10/14/15-Set flo-thru frac plug @ 8590' MD. Perf 24th stage 8409'-8563'- with 24, 0.40" holes. Frac MANCOS 24th stage with 214,120#, 20/40 PSA Sand Set flo-thru frac plug @ 8390' MD. Perf 25th stage 8203'-8357'- with 24, 0.40" holes. Frac MANCOS 25th stage with 214,237#, 20/40 PSA Sand Set flo-thru frac plug @ 8180' MD. Perf 26th stage 7997'-8153'- with 24, 0.40" holes. Frac MANCOS 26th stage with 213,402#, 20/40 PSA Sand 10/15/15-Set flo-thru frac plug @ 7970' MD. Perf 27th stage 7791'-7945'- with 24, 0.40" holes. Frac MANCOS 28th stage with 214,286#, 20/40 PSA Sand Set flo-thru frac plug @ 7700' MD. Perf 29th stage 7385'-7741'- with 24, 0.40" holes. Frac MANCOS 28th stage with 214,286#, 20/40 PSA Sand 10/16/15-Set flo-thru frac plug @ 7560' MD. Perf 29th stage 7379'-7535'- with 24, 0.40" holes. Frac MANCOS 29th stage with 213,939#, 20/40 PSA Sand Set flo-thru frac plug @ 7350' MD. Perf 30th stage 7173'-7327'- with 24, 0.40" holes. Frac MANCOS 30th stage with 215,345#, 20/40 PSA Sand Set flo-thru frac plug @ 7150' MD. Perf 31st stage 6967'-7121'- with 24, 0.40" holes. Frac MANCOS 31st stage with 213,518#, 20/40 PSA Sand Set flo-thru frac plug @ 6940' MD. Perf 32nd stage 6761'-6915'- with 24, 0.40" holes. Frac MANCOS 32nd stage with 213,518#, 20/40 PSA Sand Set flo-thru frac plug @ 6530' MD. Perf 33nd stage 6555'-6711'- with 24, 0.40" holes. Frac MANCOS 33nd stage with 214,307#, 20/40 PSA Sand Set flo-thru frac plug @ 6530' MD. Perf 34th stage 6349'-6503'- with 24, 0.40" holes. Frac MANCOS 35th stage with 214,641#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 35th stage 6138'-6299' with 24, 0.40" holes. Frac MANCOS 35th tage with 214,538#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 35th stage 6138'-6299' with 24, 0.40" holes. Frac MANCOS 35th tage with 214,538#, 20/40 PSA Sand Set flo-thru frac plug @ 6330' MD. Perf 35th stage 6138'-6299' with 24, 0.40" holes. Frac MANCOS 35th tage with 214,538#, 20/40 PSA Sand Set flo-thru frac plug

10/18/15-10/22/15- RDMO & WAIT FOR DO OPERATIONS

10/23/15- MIRU . Pressure Tested BOP- OK.

DO CBP @ 5990'. DO flo- thru Frac plug @ 6330', 6530', 6730', 6940', 7150', 7350', 7560', 7770', 7970' & 8180'

10/24/15-DO flo- thru Frac plug @ 8390', 8590', 8800', 9000', 9220', 9415', 9625', 9820', 10030', 10240', 10450', 10644', 10856', 11062 & 11270'

10/25/15-DO flo- thru Frac plug @ 11470', 11680', 11880', 12092', 12300', 12514', 12750', 13001' & 13254'

10/26/15-Land well at 5982' w/ 14.5' KB as follows, 1/2 MS, 1 Jt of 2.375" L80 tbg, 1.78" RN set at 5948', 4 Jts of 2.375" L80 tbg, 7" AS1-X Pkr set at 5816' w/ 10K in Tension, On/Off Tool at 5809', 4' pup jt, 1 Jt 2.375" L80 tbg, GLV #1 set at 5770', 5 Jts of 2.375" L80 tbg, 1.87" XN set at 5603', 13 Jts of 2.375" L80 tbg, GLV #2 set at 5181', 14 Jts of 2.375" L80 tbg, GLV #3 set at 4724', 14 Jts of 2.375" L80 tbg, GLV #4 set at 4264', 15 Jts of 2.375" L80 tbg, GLV #5 set at 3771', 14 Jts of 2.375" L80 tbg, GLV #6 set at 3311', 14 Jts of 2.375" L80 tbg, GLV #7 set at 2851', 16 Jts of 2.375" L80 tbg, GLV #8 set at 2329', 17 Jts of 2.375" L80 tbg, GLV #9 set at 1774', 21 Jts of 2.375" L80 tbg, GLV #10 set at 1089', 33 Jts of 2.375" L80 tbg, Total 182 Jts of 2.375" L80 tbg in well, lock down tbg hanger 10/27/15- OIL delivered

WILL FILE FLOWTEST INFO ON GAS DELIVER SUNDRY