

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 258-1607
Facility Name: Grambling A 7	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal (NM 013861)	API No. 3004521042
------------------------------	--	---------------------------

LOCATION OF RELEASE

Unit Letter K	Section 22	Township 28N	Range 08W	Feet from the 1500	North/South Line South	Feet from the 1700	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.643769 Longitude -107.671644

NATURE OF RELEASE

Type of Release Produced Water / Hydrocarbon	Volume of Release 5bbl/1bbl	Volume Recovered 6bbl
Source of Release Pit Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 02/29/16 @ 11:25 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	



OIL CONS. DIV DIST. 3
MAR 07 2016

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Human Factor caused an Over-the-Top release on a pit tank into the intact and impermeable lined cribbing. Water truck recovered all fluids

Describe Area Affected and Cleanup Action Taken.*
No soil affected. No remediation needed. Cribbing was well lined with an intact and impermeable liner – no integrity issues found during in-situ inspection of liner. All fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 03/08/2016	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval: —	Attached <input type="checkbox"/>
Date: March 2, 2016	Phone: (505) 258-1607	

* Attach Additional Sheets If Necessary

NVF1606886119



