Submit 3 Copies To Appropriate District Office	State of New M		Form C-103 Revised May 08, 2003
District Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II ON CONCERNATION DIVISION		30-045-29644	
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.	
87505 SUNDRY NOTIC	ES AND REPORTS ON WELL	S	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			CUCCIA STATE COM
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
1. Type of Well:			8. Well Number
Oil Well Gas Well Other			#7
2. Name of Operator			9. OGRID Number
XTO ENERGY INC.			167067
3. Address of Operator 2700 FARMINGTON AVE, SUITE K-1, FARMINGTON, NM 87401			10. Pool name or Wildcat BASIN FRUITLAND COAL
4. Well Location			
Unit Letter: K: 1565 feet from the SOUTH line and 1620 feet from the WEST line			
Section 32 Tow	nship 27N Range	08W NMPM	County SAN JUAN
	11. Elevation (Show whether Di		
6279' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON 🛛	REMEDIAL WOR	SEQUENT REPORT OF: K □ ALTERING CASING □
Y EN GIAM NEIMEDINE WORK	1 EGG AIND ADAINDOIN 2	INCINIEDIAL WOR	ALILINING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	ABANDONMENT ND
	COMPLETION	CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
XTO Energy Inc. plans to plug & abandon this well per the following:			
1. MO & RU pulling unit. NU BOP. TOH w/1-1/4" tbg. TIH to 2,218'. Pump 40 bbls water.			
1. Mo & Ro paining aint. No Bot. 1011 W/1-1/4 tog. 1111 to 2,218. Family 40 bots water.			
2. Plug #1 fr/2,218' - 1,665' w/56 sx Type II cmt (30% excess, long plug) to cover PC & FTC tops.			
3. PUH & WOC. TIH & tag cmt. Circulate well clean. Pressure test to 500#. PUH to 1,553'.			
4. Plug #2 fr/1,553' - 1,339' w/20 sx Type II cmt to cover KT & OA. PUH to 270'.			
5. Plug #3 fr/270' to surface w/approximately 25 sx Type II cmt. TOH & LD tbg.			
6. ND BOP & cut off WH. Fill csg & annulus as necessary then install P&A marker. RD & MOL.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE: Comment of the Signature: Title: REGULATORY SUPERVISOR DATE: 7/2/03			
Type or print name DARRIN STEED Telephone No. 505-324-1090			
(This space for State use) JUN - 3 2003			
A GAS INSPIRA			
Conditions of approval, if any:			