

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-31- 20395 20778
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. Fee
7. Lease Name or Unit Agreement Name Farris <u>Homestead</u>
8. Well Number 003 2
9. OGRID Number
10. Pool name or Wildcat Seven Lakes
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6540' GI

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Farris Mines (Pre-Ongard)

3. Address of Operator
419 Palomino Lane, Bloomfield, NM 87413 505-632-8438

4. Well Location
 Unit Letter P, 330 feet from the S line and 980' feet from the E line
 Section 18 Township 18N Range 10W NMPM McKinley County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- DOWNHOLE COMMINGLE
- CLOSED-LOOP SYSTEM
- OTHER:
- PLUG AND ABANDON
- CHANGE PLANS
- MULTIPLE COMPL

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING/CEMENT JOB
- OTHER:
- ALTERING CASING
- P AND A

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Farris Mines Plugged and Abandoned this well on May 11, 2016 per the attached report by A-Plus Well Service.

Plug #1 with 50 sxs (59 cf) Class B cement from 396' to surface circulate good cement out 5-1/2" casing. Tag TOC at 48'.
 Plug #2 with 10 sxs Class B cement top off casings and install on P&A marker with coordinates N 35° 47' 3" W 107° 56' 9".

- 5/10/16 Rode rig and equipment to location. RU rig and equipment. NU 5-1/2" x 8-5/8" tubing head and 8-5/8" companion flange. NU BOP and function test. Round trip 5-1/2" string mill to 398' and tag. TIH to 396'. Circulate well clean. Spot plug #1 with TOC at surface. LD all tubing. ND BOP. RD and MOL.
- 5/11/16 Travel to location. Tag TOC down 48' in 5-1/2" casing. Cut off wellhead. Spot plug #2 top off casings and install on P&A marker with coordinates N 35° 47' 3" W 107° 56' 9". SDFD.
- 5/12/16 Travel to location. Rode rig and equipment to A-Plus yard.

OIL CONS. DIV DIST. 3

MAY 31 2016

Spud Date:

Rig Release Date:

**Abandoned well inadvertently plugged by Farris Mines*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill Randall TITLE A-Plus Field Supervisor DATE 5/26/16

Type or print name Bill Randall E-mail address: billr@apluswell.com PHONE: 325-2627

For State Use Only

APPROVED BY: Bob Bell TITLE Deputy Oil & Gas Inspector, District #3 DATE 10/5/16

Conditions of Approval (if any): AV