



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**  
Cabinet Secretary

**Lori Wrotenbery**

Director

**Oil Conservation Division**

June 25, 2003

Gary Brink  
Energen Resources  
2198 Blmfld Hwy  
Farmington NM 87410

RE: Incomplete Bradenhead test reports.

Dear Mr. Brink:

The Bradenhead test on the following list of wells does not provide the information required for a complete test. Please review the bradenhead testing procedures, retest the wells and submit a complete test form before July 15, 2003.

<sup>30-045-07360</sup>  
Hancock 8, the submitted test form has no pressures on it at all.

<sup>30-045-05870</sup> ~~DE NA HAZZA 1~~, the submitted test form does not indicate a bradenhead pressure.

<sup>30-45-11676</sup> ~~TIBBAR FEDERAL 1~~, the submitted test form does not indicate a bradenhead pressure.

<sup>30-045-29141</sup> ~~TIBBAR FEDERAL 1E~~, the submitted test form does not indicate a bradenhead pressure.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: CTP  
Well File