

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other *W.W.*

2. Name of Operator

Hart Oil and Gas Inc.

3a. Address

P.O. Box 307 - Farmington, N. M. 87499

3b. Phone No. (include area code)

(505) 326-1163

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FSL & 990' FWL

TWP/LAT RGE/LON SEC QTR
31N 17W 17 NWSW

5. Lease Serial No.

14-20-603-2033

6. If Indian, Allottee or Tribe Name

Navajo Tribal

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Navajo TI "G" #223

9. API Well No.

300451106100S1

10. Field and Pool, or Exploratory Area

Horseshoe Gallup

11. County or Parish, State

San Juan, N. M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- | | | | |
|---|--|--|---|
| ☐ Acidize | ☐ Deepen | ☐ Production (Start/Resume) | ☐ Water Shut-Off |
| ☐ Alter Casing | ☐ Fracture Treat | ☐ Reclamation | ☐ Well Integrity |
| ☐ Casing Repair | ☐ New Construction | ☐ Recomplete | ☐ Other |
| ☐ Change Plans | ☒ Plug and Abandon | ☐ Temporarily Abandon | |
| ☐ Convert to Injection | ☐ Plug Back | ☐ Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plugged on 04-18-03.
(See attached)



2003 JUN -3 PM 3:24
070 Farmington, NM

RECEIVED

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Gina M. Saied

Title

VICE-PRESIDENT

Signature

Gina M. Saied

Date

05/31/03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

PTED FOR RECO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

JUN 05 2003

NMOCD

FARMINGTON FIELD OFFICE
sm

Daily Report

A - PLUS WELL SERVICE

15626

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211Rig No 119Date Wed 4-16-03Well No NAVAJO G# 223 Location _____Company HART OIL & GAS

FROM	TO	DESCRIPTION OF OPERATION
7:00	8:00	TRAVEL TO LOC.
8:00	9:00	Single 28-3/4" RODS in the Hole & 1-6' SUB SPACE well out.
9:00	10:00	P-u LOC R-D mol. (3 HRS)
		NAVAJO G# 223
10:00	10:45	ROAD RIG & EQUIP TO LOC.
10:45	11:15	R-u RIG
11:15		BACK OFF 7" CSG HEAD & 2 3/8" CSG L-D 7" CSG HEAD P-u / JT 2 3/8"
	1:00	CSG & SCREW IN TO 7" CSG
1:00	1:15	R-u PUMP TRUCK.
1:15	1:30	WAIT ON WATER TRUCK.
1:30	2:00	PUMP 5 BBLS WATER O-A 2 3/8" CSG & BORE CIRCULATION OUT 7" CSG
2:00	2:30	R-D PUMP TRUCK & DRAIN. 50FWS
2:30	3:30	TRAVEL TO FARMINGTON.

Fuel & Motor Oil _____ Water Hauled _____
 Rental Equipment _____ Cement Retainers _____
 Cementing _____
 Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	50		
Operator	S. STUART	20		8 1/2
Helper	B. STUART			8 1/2
Helper	CORY COPE			8 1/2
Helper				

Date 4-16-03

15627

Date Thu 4-17-03

FROM	TO	DESCRIPTION OF OPERATION
6:00	7:00	TRAVEL TO LOC.
7:00	7:30	START Rig & equip. HOLD SAFETY mtg (Topic) N-U
7:30	9:00	N-U 2 7/8" HEAD & STRIPPING HEAD XO FOR 1 1/4" TBG.
9:00	9:45	TALLY & P-U 1 1/4" I.T. A-Plus WORKSTRING & TAG SOAD @ 1,185'
9:45	10:15	R-U CEMENT EQUIP.
10:15		BREAK CIRCULATION OUT THE 2 7/8" CSG WITH 2 BBLS WATER. CIRC OUT
	11:00	BLACK WATER WAIT ON WATER TRUCK TO CIRC INTO.
11:00	11:15	PLUS #1 MIX & PUMP 30 SKS CEMENT, ^{15.6"} FROM 1,185' TO TAG @ 96'
11:15	11:45	L-O ALL THE TBG.
11:45	12:15	R-O CEMENT EQUIP. MOB.
2:15	2:45	ROAD CEMENT EQUIP TO LOC.
2:45	3:00	T.H. TAG TAG @ 500'. P.U.H. Perf 3-1 1/16" HOLES @ 82'
3:00	3:30	R-O FLOOR & TBG EQUIP.
3:30		BREAK CIRCULATION OUT THE B-H WITH 6 BBLS WATER. PLUS #2
		MIX & PUMP 32 SKS CEMENT, ^{15.6"} FROM 82' WITH GOOD CEMENT RETURNS
	4:00	OUT THE B-H. SHUT WELL IN SOAD.
		(7 HRS)

ANDY S. w/ HART & w/ Ashby w/ BLM & B. Freeman w/ EPA ON LOC.

Cementing P-#1-30 ^{15.6"} SKS P-#2-32 ^{15.6"} SKS

Wireline 3-1 1/16 Holes @ 8.2' W-L B.S

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	50		
Operator	S. STUART	20		7
Helper	B. STUART			7
Helper	C. CLARK			7
Helper				

Date 4-17-03

Company MART OIL & GAS.

Travel
1 1/2 hr

Wireline

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	R. Whiteley	50		
Operator	S. STUART	20		2 1/2
Helper	C. CLACK			2 1/2
Helper	M. HIGDON make markers LHC			3 1/2
Helper				
Trainee				