

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

Form C-141
Revised August 8, 2011

OCT 27 2017

Submit 1 copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Hilcorp Energy Company	Contact Lindsay Dumas
Address 1111 Travis St. Houston, TX 77002	Telephone No. (281)794-9159
Facility Name: Medio Canyon 7	Facility Type: Oil Well

Surface Owner Jicarilla	Mineral Owner Jicarilla	API No. 3003925089
--------------------------------	--------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter E	Section 35	Township 24N	Range 04W	Feet from the 2310'	North/South Line North	Feet from the 660	East/West Line West	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------------

Latitude **36.26764** Longitude **-107.23267**

NATURE OF RELEASE

Type of Release Oil	Volume of Release 3 bbls	Volume Recovered 2 bbls
Source of Release Low side of separator	Date and Hour of Occurrence 10/7/18 - 10/9/17	Date and Hour of Discovery 10/9/17
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jicarilla	
By Whom? Lisa Hunter	Date and Hour 10/10/17	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The release was from a hole in the fire tube on the low side of the separator. The heavy oil sprayed on location, covering a large surface area; 2 bbls of oil were recovered.

Describe Area Affected and Cleanup Action Taken.*

Approximately 100 c/yds of soil have been removed to date. Sampling has been scheduled for 10/24/17.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 11/7/17	Expiration Date:
E-mail Address: Ldumas@hilcorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/23/2017 Phone: (281)794-9159	<i>Sample for TPH (DO-GO-100)</i> <i>BTex and DANCE</i>	

* Attach Additional Sheets If Necessary

#NCS 1731132012

①