Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT MAY 2 1 2013 5. Lease Serial No.

FORM APPROVED

OMB No. 1004-0137 Expires: July 31, 2010

NIMOT 070204

		NIV	NIVISF-078281				
SUN	DRY NOTICES AND REPO	6. If Indian, Allottee or Tribe	Name				
Do not use	this form for proposals	Office					
ahandanad	well. Use Form 3160-3 (A	PD) for such proposals	Je mont				
abandoned	well. Use Form 3 100-3 (A	(PD) for such proposals.					
SU	BMIT IN TRIPLICATE - Other ins	tructions on page 2.	7. If Unit of CA/Agreement, N	Jame and/or No.			
1. Type of Well							
Oil Well X	Gas Well Other		8. Well Name and No.				
0.1 1101				an 29-5 Unit 24A			
2. Name of Operator			9. API Well No.	20 0 01111 2-171			
2. Traine of Operator	Hilcorp Energy Compa	any		30-039-26910			
3a. Address	Tillcorp Energy Compa	3b. Phone No. (include area code)	10. Field and Pool or Explora				
	188 07440			•			
382 Road 3100, Aztec, N	IWI 87410	505-599-3400	Gobenador F	Gobenador PC/Blanco Mesaverde			
4. Location of Well (Footage, Sec., T., R.	,M., or Survey Description)	11. Country or Parish, State	11. Country or Parish, State				
Surface Unit H (S	ENE) 1821'FNL & 520' FE	Rio Arriba	, New Mexico				
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE, REPORT OR OTH	IER DATA			
TYPE OF SUBMISSION		TYPE OF	ACTION				
THE CHOODINIOOICIV	_	111 E 01	AOTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off			
	Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	X Recomplete	Other			
- GK	Change Plans	Plug and Abandon	Temporarily Abandon				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal				
13. Describe Proposed or Completed Op	eration: Clearly state all pertinent det	ails, including estimated starting dat	e of any proposed work and approxi	mate duration thereof.			

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company plans to recomplete the subject well in the Pictured Cliffs formation and downhole commingle the existing Mesaverde with the Pictured Cliffs. Attached is the PC C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved before the work proceeds. A closed loop system will be utilized.

> SEE ATTACHED FOR CONDITIONS OF APPROVAL

NMOCD MAY 2 4 2018 DISTRICT 111 BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

> Notify NMOCD 24 hrs prior to beginning operations

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	Т				
Etta Trujillo	Title	Operations/Regulatory	Technician - Sr.		
Signature Signature	Date	5-18-18			
O THIS SPACE FOR FEE	DERAL O	R STATE OFFICE USE			
Approved by William Tambekon		Title Petroleum	Engineer	Date	5/22/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant of	or certify				-//
that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	Office FFO	•			
Title 18 II S C Section 1001 and Title 43 II S C Section 1212 make it a crime for any	nerson know	vingly and willfully to make to an	v denartment or agency	v of the IIr	nited States any

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

<u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 252333

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-26910	2. Pool Code 77440	3. Pool Name GOBERNADOR PICTURED CLIFFS (GAS)
4. Property Code	5. Property Name	6. Well No.
318837	SAN JUAN 29 5 UNIT	024A
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6622


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
Н	17	29N	05W		1821	N	520	E	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	12. Dedicated Acres 320.00 E/2		13. Joint or Infill		14. Consolidation	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations/Regulatory Tech

Date: 5/18/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Henry P. Broadhurst

Date of Survey:

8/14/2001

Certificate Number:

11393




HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 24A PICTURED CLIFFS RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 3,625'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 3,770' to isolate the Mesa Verde. Note: TOC at 3,140' by CBL.
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Pictured Cliffs in a single stage (Top Perforation @ 3,568'; Bottom Perforation @ 3,638').
- 7. Isolate frac stage with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 10. Clean out to Mesa Verde isolation plug and, when water and sand rates are acceptable, flow test the Pictured Cliffs.
- 11. Drill out Mesa Verde isolation plug and cleanout to PBTD of 6,168'. TOOH.
- 12. TIH and land production tubing. Get a commingled Mesa Verde/Pictured Cliffs flow rate.



HILCORP ENERGY COMPANY SAN JUAN 29-5 UNIT 24A PICTURED CLIFFS RECOMPLETION SUNDRY





United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



CASING REPAIR, WORKOVER, AND RECOMPLETION CONDITION OF APPROVAL

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. If a CBL or other logs are run, provide this office with a copy.
- 3. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minutes test period. Provide test chart with your subsequent report of operations
- 4. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 5. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.