RECEIVED

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

AUG 0 1 2013

FORM APPROVED OMB No. 1004-0137 expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS to Field Office 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an inagement

Expires. January 31, 2018				
5. Lease Serial No.				
N0-G-1312-1809				

SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well	TINTRIPLICATE - Other mate	ructions on page 2	NMNM 135217A		
	☐Gas Well ☐Other		8. Well Name and N Escavada Unit		
2. Name of Operator			9. API Well No.		
Enduring Resources IV, LLC 3a. Address		3b. Phone No. (include area co	30-043-21285 ade) 10 Field and Pool	or Exploratory Area	
332 Cr 3100 Aztec, NM 8741	.0	505-636-9743	Escavada N; Mai		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description, SHL: 1900' FSL & 1275' FEL Sec 10 T22N R7W Unit: I BHL: 2264' FSL & 2358' FWL Sec 4 T22N R7W Unit: K)	11. Country or Par Sandoval, NM	11. Country or Parish, State Sandoval, NM	
12.	CHECK THE APPROPRIATE I	BOX(ES) TO INDICATE NATU	RE OF NOTICE, REPORT OR C	THER DATA	
TYPE OF SUBMISSION		T	YPE OF ACTION		
□ Notice of Intent	Acidize	Deepen	☐Production(Start/Resume)	☐ Water ShutOff	
INotice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	Reclamation	☐ Well Integrity	
Subsequent Beneat	☐ Casing Repair	☐ New Construction	Recomplete	⊠Other <u>Re-install</u>	
Subsequent Report	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	GLV/Clean out	
Final Abandonment Notice	Convert to Injection		☐ Water Disposal		
60P		☐Plug Back	_ water proposed		
directionally or recomplete horizont- provide the Bond No. on file with B completion or recompletion in a new	tally, give subsurface locations and me BLM/BIA. Required subsequent repor	easured and true vertical depths of all ts must be filed within 30 days follow ed once testing has been completed.	pertinent markers and zones. Attach the tring completion of the involved operation of the involved operational Abandonment Notices must be for a superficient of the triangle of the triangle of the triangle of the triangle	ne Bond under which the work will be perfor tions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont: provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a	ally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be file	easured and true vertical depths of all ts must be filed within 30 days follow ed once testing has been completed. I he site is ready for final inspection.)	pertinent markers and zones. Attach the tring completion of the involved operation of the involved operational Abandonment Notices must be for a superficient of the triangle of the triangle of the triangle of the triangle	ne Bond under which the work will be perfortions. If the operation results in a multiple	
directionally or recomplete horizont- provide the Bond No. on file with B completion or recompletion in a new	ally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fil- and the operator has determined that the	easured and true vertical depths of all ts must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.)	pertinent markers and zones. Attach the tring completion of the involved operation of the involved operational Abandonment Notices must be for a superficient of the triangle of the triangle of the triangle of the triangle	ne Bond under which the work will be perfon- tions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont. provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a //28/18- MIRU //29/18-7/30/18- Clean out //31/18- Landed tubing @ 5473	ally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fill and the operator has determined that the subsequence of the subsequence	easured and true vertical depths of all ts must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.) NMOCD AUG 0 7 2018	pertinent markers and zones. Attach the thing completion of the involved operarinal Abandonment Notices must be find. ACCEPT	ne Bond under which the work will be perfortions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont. provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a //28/18- MIRU //29/18-7/30/18- Clean out //31/18- Landed tubing @ 5473 urn well over to production. RE	ally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fill and the operator has determined that the subsequence of the subsequence	easured and true vertical depths of all ts must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.) NMOGD AUG 0 7 2018 DISTRICT 111 O. Packer set @ 5280', 7 Gas	pertinent markers and zones. Attach the ving completion of the involved operational Abandonment Notices must be final Acceptation.	ne Bond under which the work will be perfortions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont. provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a //28/18- MIRU //29/18-7/30/18- Clean out //31/18- Landed tubing @ 5473 urn well over to production. RE	ally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fill and the operator has determined that the subsequence of the subsequence	easured and true vertical depths of all ts must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.) NMOGD AUG 0 7 2018 DISTRIGT 111 O. Packer set @ 5280', 7 Gastinted/Typed)	pertinent markers and zones. Attach the ving completion of the involved operational Abandonment Notices must be find ACCEPT ACCEPT Lift Valves FARMING By:	ne Bond under which the work will be perfortions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont. provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a //28/18- MIRU //29/18-7/30/18- Clean out //31/18- Landed tubing @ 5473 urn well over to production. RE	ally, give subsurface locations and me BLM/BIA. Required subsequent repor w interval, a Form 3160-4 must be fill and the operator has determined that the subsequence of the subsequence	easured and true vertical depths of all ts must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.) NMOGB AUG 0 7 2018 DISTRICT 111 O. Packer set @ 5280', 7 Gastinted/Typed) Title: Permit	pertinent markers and zones. Attach the ving completion of the involved operational Abandonment Notices must be find ACCEPT ACCEPT Lift Valves FARMING By:	ne Bond under which the work will be perfortions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont. provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a 2/28/18- MIRU 2/29/18-7/30/18- Clean out 2/31/18- Landed tubing @ 5473 arn well over to production. RE 14. I hereby certify that the foregoin accey Granillo	ally, give subsurface locations and me BLM/BIA. Required subsequent repor winterval, a Form 3160-4 must be filled the operator has determined that the operator has determined that the DMO. In gis true and correct. Name (Proceedings) is true and correct. Name (Proceedings) is true and correct.	easured and true vertical depths of all ts must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.) NMOGD AUG 0 7 2018 DISTRIGT 111 O. Packer set @ 5280', 7 Gastinted/Typed)	pertinent markers and zones. Attach the ving completion of the involved operational Abandonment Notices must be final Abandonment Notices must	ne Bond under which the work will be perfontions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont. provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a 2/28/18- MIRU 2/29/18-7/30/18- Clean out 2/31/18- Landed tubing @ 5473 arm well over to production. RE 14. I hereby certify that the foregoin accey Granillo Signature	ally, give subsurface locations and me BLM/BIA. Required subsequent repor winterval, a Form 3160-4 must be filled the operator has determined that the operator has determined that the DMO. In gis true and correct. Name (Proceedings) is true and correct. Name (Proceedings) is true and correct.	easured and true vertical depths of all its must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.) NMOGD AUG 07 2018 DISTRIGT 111 O. Packer set @ 5280', 7 Gastinted/Typed) Title: Permit Date: 8/1/18	pertinent markers and zones. Attach the ving completion of the involved operational Abandonment Notices must be final Abandonment Notices must	ne Bond under which the work will be perfortions. If the operation results in a multiple illed only after all requirements, including	
directionally or recomplete horizont. provide the Bond No. on file with B completion or recompletion in a new reclamation, have been completed a //28/18- MIRU //29/18-7/30/18- Clean out //31/18- Landed tubing @ 5473 urn well over to production. RE 14. I hereby certify that the foregoin Lacey Granillo	ally, give subsurface locations and me BLM/BIA. Required subsequent repor winterval, a Form 3160-4 must be filled the operator has determined that the operator has determined that the DMO. In gis true and correct. Name (Proceedings) is true and correct. Name (Proceedings) is true and correct.	easured and true vertical depths of all its must be filed within 30 days followed once testing has been completed. I he site is ready for final inspection.) NMOGD AUG 07 2018 DISTRIGT 111 O. Packer set @ 5280', 7 Gastinted/Typed) Title: Permit Date: 8/1/18	pertinent markers and zones. Attach the ving completion of the involved operational Abandonment Notices must be final Abandonment Notices must	TED FOR RECORD	

