NMOCD E -1: 2 n 2018 FORM APPROVED DEPARTMENT OF THE INTERIOR (August 200 OMB No. 1004-0137 BUREAU OF LAND MANAGEMENT Expires: July 31, 2010 5. Lease Serial No NM-03198 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Frost 501 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-045-28448 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 505-599-3400 **Basin Fruitland Coal** 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Unit B (NWNE) 1145' FNL & 1565' FEL, Sec. 25, T27N, R10W Surface San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity X Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Bradenhead Repair Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

11/21/2018 MIRU. BDW,PT tbg head to 300 psi, test not good. ND WH. NU kill spool & BOP. Pull tbg hngr. RIH & set tension pkr @ 60'. PT csg from 0'-60' to 500 psi, test 0 not good. Loaded BH. Communication see to BH while pressuring up on csg. Unset pkr. TOOH. RIH & set RBP @ 60'. ND BOP, ND tbg head. NU night cap. SISW, SDFD. SISW, SDFD.

11/26/2018 Perform WH repairs. PT WH, test-good. RDRR @ 18:00 hrs.

FARMINGTON FELD OFFICE

Reference; RBDMS MPK1815655587 - NMOCD directive t	o initia	te remedial activity before D	ecember 11, 2018.	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Christine Brock	Title	Operations/Regulatory Techn	nician - Sr.	
Signature Unistine Brock	Date	12/12/18		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by				
		Title	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify		Office		
that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any particle false, fictitious or fraudulent statements or representations as to any matter within its juri		wingly and willfully to make to any depa	rtment or agency of the United States any	