State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst Cabinet Secretary

Todd E. Leahy, JD, PhD Deputy Secretary Gabriel Wade, Acting Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 2/15/2019

Well information:

HILCORP ENERGY COMPANY 30-045-24018 Davis #13E

Application T	Type: A Drilling/Casing Change Location Change
Undergro	complete/DHC (For hydraulic fracturing operations review EPA bund injection control Guidance #84; Submit Gas Capture Plan form prior or initiating recompletion operations)
Oth	ner:

Conditions of Approval:

- Notify the OCD 24hrs prior to beginning operations.
- The initial CIBP must be placed no higher than 50' above the existing perforations.
- A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC.
 - o 24hr notice is required to be provided to the agencies prior to performing the MIT.
- After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing from the completion pressures.

NMOCD Approved by Signature

4/3/19 Date Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FEB 2 0 2019

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

Farmington Field Office

S. Lease Serial No.

Office

NMSF077648

Do not use	IDRY NOTICES AND REP e this form for proposals well. Use Form 3160-3 (A	to drill or to re-enter a		6. If Indian, Allottee or Tribe N	Jame			
SU	IBMIT IN TRIPLICATE - Other ins	7. If Unit of CA/Agreement, Name and/or No.						
1. Type of Well								
Oil Well	X Gas Well Other	8. Well Name and No. Davis 13E						
2. Name of Operator				9. API Well No.				
	Hilcorp Energy Compa	any		30-0	45-24018			
3a. Address		3b. Phone No. (include area c	ode)	10. Field and Pool or Exploratory Area				
382 Road 3100, Aztec, N	IM 87410	505-599-3400)	Basin Dakota				
4. Location of Well (Footage, Sec., T.,F Surface Unit L (NV	R.,M., or Survey Description) WSW) 1770' FSL & 880' FV	NL, Sec. 01, T31N, R1	2W	11. Country or Parish, State San Juan ,	New Mexico			
12. CHECK 1	THE APPROPRIATE BOX(ES	TO INDICATE NATURE	OF NO	TICE, REPORT OR OTHE	R DATA			
TYPE OF SUBMISSION		TYPE	OF AC	CTION				
X Notice of Intent	Acidize	Deepen	P	Production (Start/Resume)	Water Shut-Off			
	Alter Casing	Fracture Treat	R	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	XR	Recomplete	Other			
	Change Plans	Plug and Abandon	Т	Temporarily Abandon				
Final Abandonment Notice	Convert to Injection	Plug Back	V	Water Disposal				
Attach the bond under which the w	peration: Clearly state all pertinent de onally or recomplete horizontally, give ork will be performed or provide the ed operations. If the operation result	e subsurface locations and meas Bond No. on file with BLM/BL	sured and a	true vertical depths of all pertine red subsequent reports must be f	nt markers and zones. iled within 30 days			

Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company requests permission to recomplete the subject well in the Mesaverde and downhole commingle

Hilcorp Energy Company requests permission to recomplete the subject well in the Mesaverde and downhole commingle with the existing Dakota. Please see the attached procedure, wellbore diagram, plat and GCP. A closed loop system will be used. Interim reclamation will be performed after surface disturbing activities.



14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Amanda Walker	Title	Operations/	Regulatory Technician	ı - Sr.
Signature Wallet	Date	2/20/2019		
THIS SPACE FOR FEDE	ERAL C	R STATE OF	FICE USE	
Approved by Approved by antheway		Title	AT=M	Date 3/14/19
Conditions of approval, if any, are attached. Approval of this notice does not warrant or	certify		0	
that the applicant holds legal or equitable title to those rights in the subject lease which	would	Office	(Tie	
entitle the applicant to conduct operations thereon.			TTO	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any	person kno	wingly and willfu	illy to make to any department	or agency of the United States any

(Instruction on page 2)

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





OCD Permitting

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 263987

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name						
30-045-24018	72319	BLANCO-MESAVERDE (PRORATED GAS)						
4. Property Code	5. Property Name	6. Well No.						
318488	DAVIS	013E						
7. OGRID No.	8. Operator Name	9. Elevation						
372171	HILCORP ENERGY COMPANY	6327						


10. Surface Location

ſ	UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	ı
1	L	1	31N	12W	7	1770	S	880	, w	SAN JUAN	l

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 311.39			13. Joint or Infill	13. Joint or Infill 14. Consolidation Code 15. Order N				15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Amanda Walker

Title: Operations / Regulatory Tech Sr.

Date: 2/20/2019

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Fred B. Kerr Jr.

Date of Survey:

10/15/1979

Certificate Number:

3950



HILCORP ENERGY COMPANY DAVIS 13E MESA VERDE RECOMPLETION SUNDRY

API#:

300452401

JOB PROCEDURES

- 1. MIRU workover rig and associated equipment; NU and test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,600'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 6020' to isolate the Dakota and provide a base for the frac.
- 4. Load hole with fluid and run a CBL on the 4-1/2" casing. Verify cement bond within the Mesa Verde and confirm TOC. Review CBL results with the BLM and NMOCD and perform cmt remediation, as required. PT csa to 650 psi
- 5. Perforate the Mesa Verde. (Top perforation @ 4750', Bottom perforation @ 5520')
- 6. Frac the Mesa Verde in 2-3 stage down casing. Set frac plugs in between the stages and set a top plug above the top shot at +/- 4700'
- 7. MIRU workover rig. Nipple down frac stack, nipple up BOP and test.
- 8. TIH with a mill and drill out the top plug and the frac plugs.
- 9. Clean down to the top of the DK isolation plug at 6020'. Take Mesa Verde gas samples and send for analysis
- 10. Drill out Dakota isolation plug and cleanout to PBTD of 7,620'. TOOH.
- 11. TIH and land production tubing. ND BOPs and NU tree. Pump off expendable check.
- 12. RDMO. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY DAVIS 13E MESA VERDE RECOMPLETION SUNDRY

