

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-045-33503
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: MARTINEZ GAS COM F
8. Well Number 1F
9. OGRID Number 167067
10. Pool name or Wildcat BASIN DAKOTA/BLANCO MESAVERDE

Pit or Below-grade Tank Application ☐ or Closure ☐
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other _____

2. Name of Operator
XTO Energy Inc.

3. Address of Operator
2700 Farmington Ave., Bldg. K, Ste 1 Farmington, NM 87401

4. Well Location
Unit Letter **N** : **530** feet from the **SOUTH** line and **2734** feet from the **WEST** line
Section **24** Township **29N** Range **10W** NMPM County **SAN JUAN**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
5527'

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: SQUEEZE CEMENT ☒	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU. Perf'd sqz hls @ 4250' & 4 hls @ 4100'. TIH w/CICR & tbq. EOT @ 4020'. Rptd to HV w/OCD, left msg on cmt phone & w/M Kelly w/BLM @ 10:30 am 3/30/06 sqz perfs fr/4100'-4250' @10:00 am 3/31. Set CICR @ 4197'. PT tbq to 1500 psig for 5 min w/2 bbls 2% KCl wtr. OK. MIRU cmt Trks. Sqz perfs fr/4100'-4250'. PT pmp & lns to 2000 psig. OK. Unable to estb circ w/upr sqz hls. Ppd 4 bbls FW spcr. Sqz'd w/55 sx Class G cmt w/1% D65 & 1% D46 (15.6 ppg & 1.18 cuft/sx yield). Ppd dwn tbq w/12 bbls cmt. Sqz press incr fr/100 to 1000 psig (fnl sqz press). Stung out fr/CICR. RDMO cmt trks. Rptd to HV w/OCD @ 3:30 pm 3/31 sqz perfs @ 4100' @ 11:00 am 4/3. PT sqz to 1000 psig for 5 min. Cldn't pmp into sqz hole @ 4100'. MIRU BSSC WLJU. RIH w/GR. POH w/GR. RD w/WLU. DO cmt fr/4111'-4184'. Circ cln. Ran CBL log. Con't on attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Lorri D. Bingham TITLE REGULATORY COMPLIANCE TECH DATE 4/26/06
E-mail address: Regulatory@xtoenergy.com
Type or print name LORRI D. BINGHAM Telephone No. 505-324-1090

For State Use Only

APPROVED BY H. Villanueva DEPUTY OIL & GAS INSPECTOR, DIST. 4 DATE APR 28 2006
Conditions of Approval, if any:

BD sqz holes @ 4100'. Rptd progress to Henry Villanueva w/OCD @ 4:30 pm. PT tbg to 2000 psig for 5 min. Tstd OK. MIRU cmt trks. Sqz perfs @ 4100'. PT pmp & lns to 3000 psig. OK. PT csg to 500 psig. Sqz'd w/55 sx Class G cmt w/1% D65 & 1% D46 (15.6 ppg & 1.8 cuft/sx yield). Ppd dwn tbg w/12 bbls cmt @ 1.5 BPM & 1514 psig. Sqz press incr fr/930-2102 psig (fnl sqz press). Stung out fr/CICR. WOC. Rev'd 1.5 bbls cmt. RDMO cmt trks. Rptd to Henry V. w/OCD @ 8:45 am on 4/4 sqz perfs @ 4100' @ 11:00 am 4/4. DO cmt fr/4051'-4066', 4067'-4110', 4184'-4197', 4198'-4256'. DO CICR @ 4066' & 4197'. PT csg & sqz holes @ 4100' to 500 psig for 10 min. Tstd OK. PT csg & sqz holes @ 4100' & 4250' to 700 psig. Set RBP @ 4230'. Set pkr @ 4208'. OK. Rlsd pkr.