Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources				Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, winterars and waterar resources			WELL API NO. 30-039-2953	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of I	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE	FEE 🛣
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505\\			6. State Oil & Gas L	ease No.
87505		<u> </u>			
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPL	TICES AND REPORTS ( OSALS TO DRILL OR TO DE ICATION FOR PERMIT" (FO	EPEN <sub>I</sub> OR PLUG RM C-101) FOR S	UCH	Lease Name or Un Celso Gomes	1
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well Other DIST 3			8. Well Number	
2. Name of Operator	Cas won Guide Canal St.			9. OGRID Number	
Lone Wolf New M	exico, LLC			232512	
3. Address of Operator	Cuita 2200 D			10. Pool name or Wi	ldcat
1125 17th Street, 4. Well Location	Suite 2290 De	enver, Co	80202	Wildcat	
Unit Letter N	. 600' feet from the	South	line and 260	00 feet from t	he <u>West</u> line
Section 19	Township 3		mic and <u>20 (</u> e02E		County Rio Arriba
	11. Elevation (Show )				
		O'KB 			
Pit or Below-grade Tank Application A Pit type Croundy			<b>&gt;</b> 1000 by		200'
1.0	•	1 -	^		water 200
110 201101		V		nstruction Material	
12. Check	Appropriate Box to I	Indicate Nati	are of Notice,	Report or Other Da	ıta
PERFORM REMEDIAL WORK TEMPORARILY ABANDON TO PULL OR ALTER CASING	CHANGE PLANS		REMEDIAL WORK COMMENCE DRII CASING/CEMENT	LING OPNS. P	TERING CASING ☐ AND A ☐
OTHER:			THER:		
<ol> <li>Describe proposed or com of starting any proposed w or recompletion.</li> </ol>					
Lone Wolf New	w Mexico, LLC the following	proposes procedu	to plug re:	& abandon th	is well
2) Pick up ad	ocation & rig dditional tubi	ng and T	'ag PBTD @	1407'	
3) Spot a Bal	lanced Plug fr xs (59cu.ft.)	om PBTD	to 50'7ăb	ove the Dako	ta Top @ 1060'
4) POH to 500	O' and WOC 3 H	Irs. TIH	and Tag c	ement top. P	ressure Test
casing to 5) POH to 196		lanced F	lug from	190' to surf	ace with 22 sx
( - 0 O a - 1 C		cement. 1	OH & fill	the casing	with cement.
6) Reclaim	.) of Cl "B" o the location a	and insta	all the P&		with cement,
6) Reclaim	.) of Cl "B" of the location as	and insta	all the P&		with cement,
6) Reclaim	.) of Cl "B" of the location as	and insta	all the P&		with cement.
6) Reclaim to Cased hale Grown DCD	.) of Cl "B" of the location as Legaine Volume 24 Ho Notice	and insta lune + s	all the P&	A marker.	
6) Reclaim	the location at least the location at least leas	and insta lune + s 2 lo with	all the P&	A marker.	ertify that any pit or below-
6) Reclaim to Case L hele  Grove OCD  I hereby certify that the information	the location at least the location at least leas	and insta fune + g 2 lo wit lete to the best D guidelines [], a	all the P&	A marker.  e and belief. I further cor an (attached) alternative	ertify that any pit or below- e OCD-approved plan
6) Reclaim  Cased hale  Grow OCD  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name  Mike Be For State Use Only	the location at least the location at least leas	and insta lune + 1 2 lo with lete to the best D guidelines , a 	all the P&	and belief. I further cor an (attached) alternative anager Denewolfop. Telep	ertify that any pit or below- e OCD-approved plan □.

