UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

				0 00	2 24
			NUL 800S	8 5.1	Lease Number
				SEABILE	Jicarilla 70
1.	Type of Well		Ì	(FOIGIVE	If Indian, All. or
	Oil		070 F	ARMING	⊺ Tribe Name
				_	Jicarilla Apache
	Name of Owner, and			7.	Unit Agreement Name
2. I	Name of Operator				
	Chace Oil c/o	·			
	Golden Oil Holding Corporat	ion		8.	Well Name & Number
2	Address & Phone No. of Oper	otor		o.	Jicarilla 70 #14
J. 1	Address & Filone No. of Open	atoi			Jicarina 70 #14
	2200 Post Oak Blvd., Suite 720), Houston, TX 77027 713-626-111	0	9.	API Well No.
	Alon of Wall Frodoms Con T	' D M			30-039-22819
LOC	ation of Well, Footage, Sec., T	, K, M		10.	Field and Pool
	1935' FSL & 675' FEL, Section	22 T 24 N D 4 W Unit I			S. Lindrith Gallup-Dakota
	1935 FSE & 075 FEE, Section	33, 1-24-IN, IX-4-VV, OTHER		11.	County & State
				11.	Rio Arriba, NM
					Nio Alliba, Ni
12. 0	CHECK APPROPRIATE BOX T	O INDICATE NATURE OF NOTICE	REPORT.	OTHER D	ATA
	Type of Submission	Type of Action	.,	- 10120, -	1111111
	Notice of Intent		nge of Plans		
			/ Construction	n "	
	_X Subsequent Report		-Routine Fra		C SUN SUNG S
			ter Shut off		NECEIVED Z
	Final Abandonment	Altering Casing Cor	version to In	jection 🌾	olcons.div. 🖂
		X Other - Production Test		į	C DIST.S
13 . I	Describe Proposed or Comple	eted Operations			Manager College
		th			LIE DE DE DE
		May 8 th through 18 th . After fishing of	out the parted	tubing, th	ne casing did not test.
	ing leak(s) were found from 377				
Sinc	e the well has not produced for	several years, Golden Oil plans to d	o a 180 day e	economic	test to determine if
suffi	cient production can be realized	I to justify the expense of a major ca	sing repair w	orkover.	
If the	e production level is sub econor	nic, then the well will be promptly plu	igged and ab	andoned.	
See	the attached report for work de-	tails.			
14.	I hereby certify that the forego	eing is true and correct.			
	W. 11.				
Sign		Title Contractor		D	ate <u>June 1, 2006</u>
	William F. Clark	· ·			
/Th.	and for Foderal as Olst Off				
	s space for Federal or State Off	T'U.			Doto
	PROVED BYNDITION OF APPROVAL, if any				_ Date
CON	ADITION OF AFFROVAL, II any	•			
			*		1

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly to make to any departments of representations as to any matter within its jurisdiction.

JUN 13 2006





A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 * fax: 505-325-1211

Golden Oil Holding Corporation

Jicarilla 70 #14

1935' FSL & 675' FEL, Section 33, T-24-N, R-4-W

June 1, 2006 Page 1 of 1

Rio Arriba County, NM

Workover Report

Lease Number: Jicarilla Contract #70 API #30-039-22819

Work Summary:

5/8/06	MOL and RU.	Pull rods.	Hot oil tubing.	Pull tubing.	found	parted at 4424'	; heavy corrosion.
							, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

- 5/9/06 Tag fish at 4446'. Recovered 15' piece, parted again. Note tubing very, very corroded. Multiple holes. Heavy scale. Heavy scale in casing.
- 5/10/06 Tag fish at 4472'. Jar fish free. TOH and LD 89 joints 2.375" tubing, total 225 joints, from well.
- 5/11/06 Ran scraper, set RBP at 5720. Test casing, leak, 2 bpm at 400#.
- 5/12/06 Isolate casing leak(s) from 3774' to 4576'. Pull RBP. TIH with bit.
- 5/15/06 Circulate well with KCl water. Clean out fill from 7131' to 7335'. Set Loc Set packer at 7184' with on / off tool above.
- 5/16/06 Rods stacked out on paraffin in tubing. Hot oil again. Pull packer, replace rubber.
- 5/17/06 With packer at 7196', hot oil tubing again.
- 5/18/06 Land 226 joints 2.375" tubing at 7196' KB with Loc Set packer at 5590' and SN at 7161'. Ran 170 3/4" rods and 116 7/8" rods. Space out rod and hang off.

RD and MOL.