

1

Submit 3 Copies To Appropriate District Office	ct		New Me			Form C-	
District I 1625 N. French Dr., Hobbs, NM 88240		Energy, Minerals	and Natu	ral Resources	WELL API NO		2004
District II		OIL CONSERV	JATION	DIVISION	30-045-25029		
1301 W. Grand Ave., Artesia, NM 8821 District III	10				5. Indicate Typ		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505					STATE		
District IV		Santa Fo	e, NM 87	505	6. State Oil &	Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			1861 1 1 1 1 2 3 W				
SUNDRY NOTICES AND REPORTS ON WELLS					7 Loggo Name	e or Unit Agreement Nar	<del></del>
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					Kirtland	e or Onit Agreement Nat	ne
PROPOSALS.)		P		*************************************	8. Well Numb	er	
1. Type of Well:		u le ac	amentalis (a.e.) Amentalis		#9		
Oil Well Gas Well		other has a	e Teories III de la composición de la La composición de la	sista - i		·	
2. Name of Operator		\$5.2°	LANGER OF	- 134 	9. OGRID Nu	mber	
Richardson Operating Comp	any				019219		
3. Address of Operator		The state of the s	66014	in the same of the	10. Pool name	or Wildcat	
3100 La Plata Highway, Farr	ninate	on. <b>NM</b> 87401	Maria Maria	505-564-3100	Cha Cha Gall	up	
4. Well Location	·/····9	<u> </u>			1		
4. Well Location							
Unit LetterK	_:;	2045'feet from the	South	line and	1970'feet	from theWestI	ine
Section 1	2	Township 2	29N R	ange 15W	NMPM	County San Juan	n
		11. Elevation (Show w				County Cambridge	
		11. Dievation (biton n	5176' GL				
Pit or Below-grade Tank Application	(For p	it or below-grade tank clos			:d)		
Pit Location: UL Sect Tw	,					n nonract frach water well	
				_	<del> </del>		
Distance from nearest surface water	<u> </u>	Below-grade Tank Lo	cation UL_	SectTwj	Rng	_;	
feet from theline an	d:	feet from the	line				
I .							
<u> </u>		· · · · · · · · · · · · · · · · · · ·	<del></del>				
			<del></del>				
12. Chec	k Ap	opropriate Box to Ir	ndicate N	ature of Notice,	Report or Oth	er Data	
			ndicate N		-		
NOTICE OF	INT	ENTION TO:		SUB	SEQUENT F	REPORT OF:	
	INT	ENTION TO:			SEQUENT F	REPORT OF:	
NOTICE OF PERFORM REMEDIAL WORK	INT	ENTION TO:		SUB	SEQUENT F	REPORT OF:  ALTERING CASING	
NOTICE OF PERFORM REMEDIAL WORK	INT	ENTION TO: PLUG AND ABANDON		SUB REMEDIAL WOR	SEQUENT F	REPORT OF:  ALTERING CASING	
NOTICE OF PERFORM REMEDIAL WORK	INT	ENTION TO: PLUG AND ABANDON		SUB REMEDIAL WOR	SEQUENT F	REPORT OF:  ALTERING CASING  PLUG AND	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON	INT	ENTION TO: PLUG AND ABANDON CHANGE PLANS		SUB REMEDIAL WOR COMMENCE DR	SEQUENT F	REPORT OF:  ALTERING CASING  PLUG AND	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	INT	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE		REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB	SEQUENT F	REPORT OF:  ALTERING CASING  PLUG AND	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON	INT	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE		SUB REMEDIAL WOR COMMENCE DR	SEQUENT F	REPORT OF:  ALTERING CASING  PLUG AND	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	INT	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly	y state all p	REMEDIAL WOR COMMENCE DR CASING TEST AI CEMENT JOB OTHER: pertinent details, an	SEQUENT F  ILLING OPNS.  ND	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  I  Idates, including estimates	□ d date
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:  13. Describe proposed or co	INT	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly	y state all p	REMEDIAL WOR COMMENCE DR CASING TEST AI CEMENT JOB OTHER: pertinent details, an	SEQUENT F  ILLING OPNS.  ND	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  I  Idates, including estimates	□ d date
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or coof starting any proposed or recompletion.	mplet	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly). SEE RULE 1103.	y state all p	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Dertinent details, an le Completions: An	SEQUENT F  ILLING OPNS.  ND	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  I  Idates, including estimates	□ d date
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or coof starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ recompletion.	omplet work	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly). SEE RULE 1103. I	y state all properties.	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Dertinent details, an le Completions: Al	SEQUENT F  ILLING OPNS.  ND	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  I  Idates, including estimates	□ d date
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or coof starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ r6/27/04 TOH w/ tbg. Tbg and	omplet work	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly). SEE RULE 1103. I	y state all properties of the	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Description details, and le Completions: Al OCD. 24327'.	SEQUENT F	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  dates, including estimated agram of proposed comp	□ d date letion
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or constraint of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ ref/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement ref	omplet work rods.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. I Swab well bore. With yould not release. They of @ 4317'. TIH w/ th	y state all properties of the	SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Description details, and le Completions: Al OCD. 4327'. Into retainer. Est. I	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  dates, including estimated agram of proposed comp  500psi. Pump 75sx Cl	□ d date letion
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or constraint of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ r6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yield.	omplet work rods. hor w	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. If Swab well bore. With yould not release. Tog or @ 4317'. TIH w/ to tung out of retainer. See	y state all properties of the	COMMENCE DR CASING TEST A CEMENT JOB OTHER: Dertinent details, and le Completions: Add OCD. 0 4327'. Into retainer. Est. recement plug on to	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  dates, including estimated agram of proposed comp  500psi. Pump 75sx Cl OH w/ tbg.	□ d date letion
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or conference of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ rf 6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yie 7/2/04 Test bottom plug to 50	omplet work rods. hor w taine	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. If yould not release. The off @ 4317'. TIH w/ the tung out of retainer. Since the out of retainer. Since the out of the out.	y state all property for Multiple grout off @ g. Sting in Spot 300' to 1303'.	REMEDIAL WOR  COMMENCE DR  CASING TEST A CEMENT JOB  OTHER: Description of the completion of the compl	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  dates, including estimated agram of proposed comp  500psi. Pump 75sx Cl OH w/ tbg.	□ d date letion
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or conference of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/r 6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yie 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst	omplet work tods. hor we taine ld. Si opsi, all P&	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. If yould not release. The yould not release. The training out of retainer. See the order of the order. See the order of th	y state all property for Multiple grout off @ sting ir Spot 300' to 1303'. location.	REMEDIAL WOR  COMMENCE DR  CASING TEST AL  CEMENT JOB  OTHER:  Detrinent details, and le Completions: Al  OCD.  4327'.  Ato retainer. Est. recement plug on to Spot balanced plus prepto reclaim.	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  dates, including estimate agram of proposed comp  500psi. Pump 75sx Cl OH w/ tbg.  103'. Bring cement to	d date letion
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or conformation of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ rf 6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yie 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the information.	omplet work rods. hor w taine id. Si lopsi, all P8	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. If yould not release. The yould not release. The training out of retainer. See the owner of the owner. See the owner of the owner owner owner owner. See the owner owner. See the owner	y state all property of the state of the best of the b	REMEDIAL WOR  COMMENCE DR  CASING TEST AL  CEMENT JOB  OTHER:  Detrinent details, and le Completions: Al  OCD.  20 4327'.  Into retainer. Est. recement plug on to spot balanced plus  Prep to reclaim.  est of my knowledge	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDONMENT  Adates, including estimated agram of proposed comp  500psi. Pump 75sx Cl OH w/ tbg.  103'. Bring cement to	d date letion
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or construction of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ r6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yie 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the informat grade tank has been/will be constructed.	omplet work tods. hor wetaine ld. St lopsi, all P& ion abd	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. If yould not release. The yould not release. The training out of retainer. See the object of t	y state all property of the state of the beguidelines	REMEDIAL WOR  COMMENCE DR  CASING TEST A CEMENT JOB  OTHER: Description of the completions: And the completions of the completion of the c	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDO	d date letion
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or consistency of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/r 6/27/04 TOH w/r tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yier 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the informating rade tank has been/will be constructed.  SIGNATURE Charlos H.	omplet work tods. hor we taine ald. Si opsi, all P& ion abd or cle	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly x). SEE RULE 1103. It yould not release. The trould not release. The troug out of retainer. So held OK. TIH w/ the same and complete been according to NMOCD williams	y state all properties of the begindelines.	REMEDIAL WOR  COMMENCE DR  CASING TEST AI  CEMENT JOB  OTHER:  Detrinent details, and  Ite Completions: Ai  OCD.  20 4327'.  Into retainer. Est. recement plug on to Spot balanced plus  Prep to reclaim.  est of my knowledged, a general permit in the completion.	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDO	d date letion
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER:  13. Describe proposed or construction of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ r6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yie 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the informat grade tank has been/will be constructed.	omplet work tods. hor we taine ald. Si opsi, all P& ion abd or cle	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly x). SEE RULE 1103. It yould not release. The trould not release. The troug out of retainer. So held OK. TIH w/ the same and complete been according to NMOCD williams	y state all properties of the begindelines.	REMEDIAL WOR  COMMENCE DR  CASING TEST AI  CEMENT JOB  OTHER:  Detrinent details, and  Ite Completions: Ai  OCD.  20 4327'.  Into retainer. Est. recement plug on to Spot balanced plus  Prep to reclaim.  est of my knowledged, a general permit in the completion.	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDO	d date letion
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or consistency of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/r 6/27/04 TOH w/r tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yier 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the informating rade tank has been/will be constructed.  SIGNATURE Charlos H.	omplet work tods. hor we taine ald. Si opsi, all P& ion abd or cle	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly x). SEE RULE 1103. It yould not release. The trould not release. The troug out of retainer. So held OK. TIH w/ the same and complete been according to NMOCD williams	y state all properties of the begindelines.	REMEDIAL WOR  COMMENCE DR  CASING TEST AI  CEMENT JOB  OTHER:  Detrinent details, and  Ite Completions: Ai  OCD.  20 4327'.  Into retainer. Est. recement plug on to Spot balanced plus  Prep to reclaim.  est of my knowledged, a general permit in the completion.	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDO	d date letion
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or consistency of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/r 6/27/04 TOH w/r tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yier 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the informating rade tank has been/will be constructed.  SIGNATURE Charlos H.	omplet work tods. hor we taine ald. Si opsi, all P& ion abd or cle	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly x). SEE RULE 1103. It yould not release. The trould not release. The troug out of retainer. So held OK. TIH w/ the same and complete been according to NMOCD williams	y state all properties of the begindelines.	REMEDIAL WOR  COMMENCE DR  CASING TEST AI  CEMENT JOB  OTHER:  Detrinent details, and  Ite Completions: Ai  OCD.  20 4327'.  Into retainer. Est. recement plug on to Spot balanced plus  Prep to reclaim.  est of my knowledged, a general permit in the completion.	SEQUENT F  K	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDO	d date letion
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or consistency of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ r6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yie 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the informat grade tank has been/will be constructed.  SIGNATURE Charles //	omplet work tods. hor we taine ald. Si opsi, all P& ion abd or cle	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. If yould not release. The yould not release. The training out of retainer. See the dok. TIH w/ the BA marker. Clean up to you is true and complete to	y state all property for Multiple grout off @ grout off @ grout off @ grout off and it is to the beguidelines [TITLE	REMEDIAL WORK COMMENCE DR CASING TEST AL CEMENT JOB OTHER: Detrinent details, and le Completions: An OCD. D 4327' Into retainer. Est. or cement plug on to Spot balanced plug Prep to reclaim. Lest of my knowledged, a general permit  Completions:  Completions: An OCD. D 4327' Co	d give pertinent of tach wellbore dia rate of 3bpm at top of retainer. Tug to 1303' to 1 ge and belief. I fur or an (attached) alto 1955. Manager 1965. Manager 1965.	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDO	d date letion  ass B  below-  n   2
NOTICE OF PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or consistency of starting any proposed or recompletion. 6/26/04 Hot oil well. TOH w/ r6/27/04 TOH w/ tbg. Tbg and 7/1/04 Wireline set cement recement with 15.6ppg, 1.18 yie 7/2/04 Test bottom plug to 50 surface. Cut off wellhead. Inst I hereby certify that the informat grade tank has been/will be constructed.  SIGNATURE Charles //	omplet work tods. hor we taine ald. Si opsi, all Perion abd or cle	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  ted operations. (Clearly). SEE RULE 1103. If yould not release. The yould not release. The training out of retainer. See the dok. TIH w/ the BA marker. Clean up to you is true and complete to	y state all property for Multiple grout off @ grout off @ grout off @ grout off and it is to the beguidelines [TITLE	REMEDIAL WORK COMMENCE DR CASING TEST AL CEMENT JOB OTHER: Detrinent details, and le Completions: An OCD. D 4327' Into retainer. Est. or cement plug on to Spot balanced plug Prep to reclaim. Lest of my knowledged, a general permit  Completions:  Completions: An OCD. D 4327' Co	d give pertinent of tach wellbore dia rate of 3bpm at top of retainer. Tug to 1303' to 1 ge and belief. I fur or an (attached) alto 1955. Manager 1965. Manager 1965.	REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT  ABANDO	d date letion  ass B  below-  n   2

B