In Lieu of	
Form 3160	
(June 1990)	

## **UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT**

FORM	APPRO	OVED
udget Rure	an No	1004.

Expires: March 31, 1993

SUNDRY	NOTICE	AND	REPORTS	ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

5. Lease Designation and Serial No. SF-078767

2008 HH 17

If Indian, Allottee or Tribe Name

			1000 OOF T.L. 111	ρυι	
		SUBMIT IN TRIPLICATE	RECEIVE		If Unit or CA, Agreement Designation ROSA UNIT
1.	Type of Well Oil Well X Gas Well	Other	19 19 20 21 22 33 5 m	8.	Well Name and No. ROSA UNIT #209A
2.	Name of Operator WILLIAMS PRODUCTION (	COMPANY	E 111 2006	9.	API Well No. 30-039-27699
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TUL	SA, OK 74101 (918) 573-6254	E OLCUMA DIM.	10.	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL
4.	Location of Well (Footage, Sec 1085' FSL & 975' FEL, SW/4	c., T., R., M., or Survey Description) SE/4 SEC 24-T31N-R06W	DIST. 8	11.	County or Parish, State RIO ARRIBA, NM
	CURC	A PROCEDIA THE POST A TO DIE	C D T V C	EDODE OD C	

<u>CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA</u>

TYPE OF SUBMISSION	TYPE OF AC	TION
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
· · · · · · · · · · · · · · · · · · ·	Casing Repair	Water Shut-Off
Final Abandonment	Altering Casing	Conversion to Injection
·	Other Pumping Unit & Rod Installation	Dispose Water
		(Note: Report results of multiple completion
		on Well Completion or Recompletion Report
		and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

04-14-2006 MIRU. Bled csg & tbg down. NU rig pump, kill well w/ water, ND tree, NU BOP, function test BOP, unland tbg & tagged fill @ 7170' = 8' of fill. NU w/ air pack. Broke circ w/ 10 bph air/soap/corrosion inhibitor. Displace 15 bbls wtr. Circ fill from 3170' to PBTD @ 3178'. ND w/ air pack. TOH w/ tbg - measured and visually inspect. Made up 27/8" mud anchor w/ F-Nipple. TIH w/ kill string. SDFN

04-15-2006 Bled down and kill w/, formation wtr. TIH w/ prod string tbg. Land tbg w/ F-Nipple @ 3147' & OA @ 3147' = 4' above PBTD. ND w/ BOP. NU w/ new wellhead assembly. Rig to run rods. TIH w/ new rods and pump -- picked rods up in singles. Spaced pump. Filled tbg w/ formation water. press test tbg @ 500 psi w/ rig pump. Stroked pump to 500 psi w/ pulling unit, good pump action and tst. NU w/ pump jack and horse head! Hung well on ready for prod. Unable to start pumping unit, flowline not connected, will be connected for Monday morning start up. Load out w/ rig equip, LD rig mast and cleaned location. Turn well to production department, release rig @ 1600 hrs.

14.	I hereby certify that the foregoing is true and correct			
	Signed CLC Ross	Title Sr. Production Analyst	Date <u>July 14, 2006</u>	
	(This space for Federal or State office use)			
	Approved by	Title	Date	<del></del>
	Conditions of approval, if any:			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED TO THE COLD

JUL 2 0 2006