Submit 3 Copies To Appropriate District	State of New Mexico				Form C-103
Office District I	Energy, Minerals and Natural Resources				March 4, 2004
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION				-045-33489
District III	1220 South St. Francis Dr.			5. Indicate Type STATE	of Lease FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & G	
1220 S. St. Francis Dr., Santa Fe, NM	•	, E	5 28 37 37	o. saw on w o	Louise 110.
87505 SUNDRY NOT	ICES AND REPORTS ON	WEINE		1 Lease Name o	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLI	SCALE TO DRILL OR TO DEED	EN OR PLUG BA	an anao	المالين ا	
PROPOSALS.) 1. Type of Well:			M	8. Well Number	
Oil Well Gas Well X	Other		OUST.	577	#109S
2. Name of Operator			-Oles, .	9 OGRID Numl	
Burlington Resources Oil & Gas	Company LP	- VI	Chronat	<u> </u>	14538
3. Address of Operator P.O. Box 4289, Farmington, NM	87400_4280	44	E BE Char	10. Pool name of	r Wildcat Coal / Fruitland Sands
4. Well Location	0/477-4207			Dasin Fruitiana C	Zoal / I Tultiand Sands
. Won Location					
Unit LetterD _:	945 feet from the	North	line and _	1005 feet from t	he <u>West</u> line
Section 32	Township 32N			MPM San Juan	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
Based of China to Angles (1984). It		5876' GL			
12 01 - 1-	A	12 NT . 4	CNT . 41	D (04	. D 4.
	Appropriate Box to Inc	iicate Natur			
PERFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON		SUB: MEDIAL WORK		PORT OF: ALTERING CASING □
PERFORM REMEDIAL WORK	PLUG AND ABANDON		VIEDIAL WORF	` ⊔	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	⊠ co	MMENCE DRII	LING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		SING TEST AN MENT JOB	ID 🗆	
OTHER:		ОТ	HER:		
13. Describe proposed or com	pleted operations. (Clearly	state all pertin	ent details, and	give pertinent da	tes, including estimated date
					ram of proposed completion
•					
We are requesting permission to ch					
required. We will be drilling out under the surface using w/clean phase (vis 30-35, WT 8-5-9.0 ppg WL <20 cc/30 min). Sweep with gel/fiber as needed. Change mud vis to 45-50 before running pipe (mud uo to Vis 8-100 to run logs).					
ger/noer as needed. Change mud v	is to 45-50 before ruining j	pipe (mua uo	.o vis 8-100 to	run iogs).	
Hereby certify that the information	ahove is true and complete	to the best of	my knowledge	and belief I forth	ou coutify that any ait on halow
grade tank has been/will be/sonstructed o	r closed according to NMOCD {	guidelines [], a g	eneral permit []	or an (attached) alter	native OCD-approved plan .
SIGNATURE Patsey	1/1. (/				7/27/06 .
SIGNATURE	- Carry	IILE SI. KE	ulatory Specia	IIST DATE _	<u> </u>
Type or print name Patsy C	lugston E-mail add	ress: pclugsto	n@br-inc.com	Telephone No.	505-326-9518
(This space for State use)					
(11119 space for state use)					
7	7//				1111 0 14 2000
APPPROVED BY	=///ndT	TILE WAN	COL & GAS IN	Spector, dist. (39	DATE JUL 2 7 2006
Conditions of approval, if any:	400				 -