Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

☐ Change Plans

☐ Convert to Injection

EUD	N.A	A DDE	OVED	

Budget Bureau No. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

SF 078476

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.					7. If Unit or CA/Agreement, Name and/or No.			
SUBMIT IN	TRIPLICATE - Other	instructions on reverse side		/. H OM 01 01	or groomony rame o	110.01		
1. Type of Well ☐ Oil Well ☑ Gas V	Vell 0	ther		8. Well Name :	and No. N. Fed #10G			
2. Name of Operator Robert L. Bayless, Producer L	LC			9. API Well No 30-045-31				
3a. Address 3b. Phone No. (include area code) PO Box 168, Farmington, NM 87499 (505) 326-2659				10. Field and Pool, or Exploratory Area Basin Fruitland Coal				
4. Location of Well (Footage, Sec., T., 970' FNL & 1100' FEL, Sec. 1		aription)		11. County or Pa San Juan,	arish, State New Mexico			
12. CHECK AP	PROPRIATE BOX	(ES) TO INDICATE NATUR	E OF NOTICE, I	REPORT, OR	OTHER DATA			
TYPE OF SUBMISSION		TYPE OF	ACTION					
☐ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (S	tart/Resume)	☐ Water Shut-Off ☐ Well Integrity			
✓ Subsequent Report	☐ Casing Repair	☐ New Construction			✓ Other Spuce	l, Surface Casing		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, A Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

☐ Plug Back

☐ Plug and Abandon

☐ Temporarily Abandon

■ Water Disposal

See attached Morning Report.

☐ Final Abandonment Notice



RECEIVED

703 IN 24 M 8: 05

070 Farmington, NM

& Run Cement

14. I hereby certify that the foregoing is true and correct	1							
Name (Printed/Typed) Price M. Bayless	Title	Engineering Manager						
Signature 1- May	Date	June 23 2003	COEDTED EAD DECOR					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by	Title		JUN 2. 5 2003					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operation thereon.	Office		FARMINGTUM FIELD OFFICE					

Title 18 U.C.S. Section 1001 and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Robert L. Bayless, Producer LLC

Oxnard WN Federal #10G 970 FNL & 1100 FEL Section 15 – T17N – R8W San Juan County, New Mexico

Morning Report - Drilling

6/20/03

Build location and dig pit. Line and fence pit. Move L&B Speedrill onto location and rig up. Haul water to location. Spud well at 4:00 pm, 6/10/03. Drill 8 3/4" hole to 90 feet. Circulate hole clean and shut down overnight.

6/21/03

Continue drilling to 140 feet and circulate hole clean. Drop survey tool and trip out of hole. Deviation ¼° at 140 ft. Rig up and run 3 joints (133.42 ft) 7° 20 #/ft new J-55 ST&C casing, land at 139 ft. Rig up AES and cement surface casing with 70 sx (83 cf) Class B cement with 3% CaCl and ¼ #/sx celloflake. Good returns throughout job with 4.2 bbls circulated to pit. Plug down at 10:00 am. WOC 4 hours. Break off landing joint and make up wellhead. Nipple up BOP and pressure test, held OK. Trip in hole and tag cement. Shut down overnight.