In Lieu of Form 3160 (June 1990)

## **UNITED STATES** DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Lease Designation and Serial No.

SUNDR	Y NO	TICE A	ND REI	ORTS	ON W.	ELLS
anacala ta	drill o	e to Jaans	on or rear	tru to a c	liffarant	racamiair

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use TO DRILL" for permit for such proposals

If Indian, Allottee or Tribe Name

NMSF-078763

			0,	in indiana i inioace a contra
		<del>- 2013 00 T 23 - 6.</del> 7	U I	• 1 ]
			7.	If Unit or CA. Agreement Designation
	SUBMIT IN TRIPLICATE	<u> </u>		
1.	Type of Well Oil Well X Gas Well Other	G10 YA	8.	Well Name and No ROSA UNIT #360
2.	Name of Operator WILLIAMS PRODUCTION COMPANY		9.	API Well No. 30-039-29882
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10.	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 310' FNL & 150' FWL. NW/4 NW/4 SEC 16-T31N-R05W		11.	County or Parish. State RIO ARRIBA, NM
V.			0000 00	OTHER IS A TA

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans Notice of Intent **New Construction** Recompletion Non-Routine Fracturing X Subsequent Report Plugging Back Water Shut-Off Casing Repair Final Abandonment Altering Casing Conversion to Injection Dispose Water Other Completion (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is 13. directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

09-14-2006 MIRU. ND w/ xmas tree. NU w/ BOP, mud cross & blooie line. NU w/ air pack. Spot frac tank & fill w/ produced water. NU w/ air pack.

09-15-2006 Press tested BOP blind rams & csg @ 1500 psi for 30 min test, no leak off. Made up 6 1/4" tri-cone bit w/ 8 x 4 3/4" DC's & TIH w/ same on 2 7/8" AOH DP, measured & picked DP up in singles. Staged in hole w/ DP displacing drlg mud w/ produced water. Located top of CIBP @ 3142'. Press tested BOP pipe rams & csg @ 1500 psi for 10 min test, no leak off. NU w/ PS. Drld CIBP from 3142' to 3145' & fell thru to 3150'. Drilling on CIBP remnant & spinning on top of wiper plug. Circulated wellbore clean. Tripped up hole & hung off @ 3130'. SDFN.

09-16-2006 Broke circ w/ produced water. Drilled from 3150', fighting CIBP remnant & wiper plug to float collar @ 3200'. DO float collar, had cmt void to 3212'. Drilled hard solid cement from 3212' to float shoe @ 3239'. DO float shoe & fell thru to 3248'. Circ clean & ND w/ PS. TOOH w/ drilling assembly. Replaced bit w/ new 6 1/4" tri-cone button bit. TIH w/ same on 10 x 4 3/4" DC's & 2 7/8" AOH DP. Hung off inside 7" csg @ 3200'. Ready to DO & mud log Monday morning. RD until Monday, 9-18-06.

Continued on Back

14.	I hereby certify that the foregoing is true and correct Signed Tracy Ross	Title Sr. Production Analyst	Date	October 19, 2006
	(This space for Federal or State office use)			
	Approved by	Title		Date
	Conditions of approval, if any:			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulen statements or representations as to any matter within its jurisdiction. ACCEPTED FOR RECORD



NOV 0 1 2006

<u>09-18-2006</u> MI & off load 3.5 power swivel. NU w/ 3.5 power swivel. Single out w/ drill line. MIRU Coquette mud loggers equip. TIH & tagged up @ 3244'. Drilled & mud logged from 3244' to 3506'. Basal @ 3383' to 3486'. Bottom of coal 3406'. Logged a total of 30' coal. Recorded gas from 7225 to 2000 units. Circulated wellbore clean & rigged out w/ mud loggers equip. ND w/ power swivel & doubled up drill lines. TOOH to 1700' & NU w/ air pack. Displaced wellbore fluid w/ air. ND w/ air pack. TIH to 3506'. NU w/ air pack & displaced wellbore fluid w/ air. ND w/ air pack. TOOH & hung off drill assembly in 7" csg @ 3200'.

<u>09-19-2006</u> Csg = 920 psi. Bled down. TOH w/ DP & drill assembly. MI & off load Knight underreamer equip. MU 5 ¾" Knight underreamer w/ 9 1/2" PDC blades. TIH w/ same on 10 DC's & 2 7/8" DP. NU w/ air pack & broke circ w/ 12 bph air. Underreamed from 3248' to 3506'. Misting w/ 12 bph water & recovering 35 bph water. Circ @ 3506', circ w/ air pulling from 3506' to 3380'. Circ w/ air, unable to dry up hole, recovering 8 bph water. TUH & hung off in 7" @ 3200'. SDFN.

 $\underline{09\text{-}20\text{-}2006}$  Csg press 1200#. Bled down & purged of air. Made pitot = 217 mcfd. ND & load out w/ 3.5 power swivel. TOH w/ underreamer assembly. LD 2 7/8" DP & 10 x 4  $\frac{3}{4}$ " DC's. Loaded out w/ Knight underreamer. TIH & land 106 jts 2-7/8", 4.6#, J-55 tbg @ 3235' as follows: mule shoe on bottom, 1 jt tbg, 2.28" "F" nipple @ 3202' & 105 jts tbg. (4' inside intermediate csg) ND blooie line & BOP. NU w/ xmas tree. Antelope test @ 2000#. Turn well to production department, release rig.