
## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



\_\_\_ Non-Routine Fracturing

Conversion to Injection

\_ Water Shut off

Sundry Notices and Reports on Wells Lease Number NMSF-078781 If Indian, All. or 6. 1. Type of Well GAS Tribe Name n/a Unit Agreement Name 2. Name of Operator n/a ConocoPhillips Company Well Name & Number Bruington LS #4M 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 API Well No. 30-045-33877 10. Field and Pool 4. Location of Well, Footage, Sec., T, R, M 2075' FSL, 2155' FEL, Section 6, T30N, R11W 36° 83975'N, 108° 03032'W Blanco MV / Basin Dakota 11. County and State San Juan Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Abandonment \_ Change of Plans \_\_X\_ Notice of Intent \_ Recompletion New Construction

13. Describe Proposed or Completed Operations

Subsequent Report

Final Abandonment

Bruington LS #4M road re-route to run easterly along south side of power line.

\_ Plugging Back

\_ Casing Repair \_\_ \_ Altering Casing \_\_

Other

/u/ .1

NMOCD  $\beta^{(1)}/4/\alpha_0$