D NOU 16'06 CONS. DIV. DIST. 3

	UNITED S	STATES			FORM APPROVED	
Form 3160-5	DEPARTMENT OF				Budget Bureau No. 1004-0135	
(June 1990)	BUREAU OF LAND		tastas		Expires March 31, 1993	
(oute 1990)	39/12/13 3/ 2/ 11/2	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		· 4 11	5 Deage Designation and Serial No.	
	SUNDRY NOTICES AND	REPORTS ON WELLS	2006 NOV	17	FTI 12 23	
					NMNM-99735	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE 070 FARM					NGTON NM	
1. Type		MIFLIONIL	0101	ATOM	7. If Unit or CA, Agreement Designation	
					The state of the s	
c	il Well X Gas Well	Other		L		
					8. Well Name and No.	
2. Name	e of Operator	OGRID (16348)			Synergy 21-7-7 # 135	
Synergy Operating, LLC				F	9. API Well No.	
	ess and Telephone No.				0.74 F 770H 140.	
					30-043-21021	
P.O. Box 5513, Farmington, NM 87499 (505) 325-5449					10. Field and Pool, or Exploratory	
4. Location of Well (Footage, Sec, T. R., M, or Survey Description)						
					Basin Fruitland Coal	
Unit K, 1775' FSL, 1960' FWL, Sec 07, T21N - R07W					11. County or Parish, State	
220 E6 parca (M/2)					Sandoval County NM	
320.56 acres (W/2) 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OF				T OR	Sandoval County, NM	
TYPE OF SUBMISSION TYPE OF ACTION						
				_	1, 2	
	Notice of Intent	Abandome			Change of Plans	
ভো	Octobros de Donne d	Recompleti		X	New Construction	
L.	Subsequent Report	Plugging Ba		\vdash	Non-Routine Fracturing Water Shut-Off	
	Final Abandonment Notice	Casing Rep		H	Converion to Injection	
	That Abandonnent House	Other	Sing	H	Dispose Water	
					(Note: Report results of multiple compleiton on Well	
					Completion or recompletion Report and Log Form)	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work.						
If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work.						
06-29-2006	MIRU Silver Star Rig # 12. ND W	/H. NU 3000# BOP. w/ (Chart Recorder.	Test 5-	1/2" 15.5# Production Casing to 1500#.	
Hold and Chart 30 mins. Good Test. RU Floor. Strap & GIH w/ 24 Jts 2-3/8" 4.7# tubing. Tag @ 776' PBTD. COOH.						
RU Blue Jet w/ pack-off. Perforate Fruitland Coal w/ 4 SPF from 515' to 537' (22'), 88 h					88 holes. RD Blue Jet.	
SDFN.						
00.00.0000 014.0014						
06-30-2006 SM. GIH and land 22 Jts - 2-3/8" 4.7# J-55 Production tubing at 748' KB. ND BOP. NU Wellhead. RU swab equipment.						
Swab well in making 16 runs, recover 40 bbls fluid to rig pit. RD and Prep for Rig move to Synergy 21-7-7 # 136 well.						
	Final Report this phase.					
THE RESIDENCE OF THE PROPERTY						
Awaiting BH Pressure Measurement and Pump Jack Installation Plan to pump well prior to any sort of fracture stimulation					ACCEPTED FOR RECORD	
					NOV 4 F cocc	
					NOV 1 5 2006	
ALL A PT LANGUAL CO COSA-1						
need PT for surface cog/					BY IL Salvers	
14. I hereby certify that the foregoing is true and object						
Signed: Title: Engineering Manager Date: 11-10-2006						
Thomas. E. Mullins tom.mullins@synergyoperating.com This space for federal or state office use						
This space for redeficion state unition use						
Approved by:		Ti	tle:		Date:	
Conditions of approval if any						

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements