

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

DIST. 3

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

SF - 078195

6. Indian, Allottee or tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

8. Well Name and No.

Sellers Federal LS 2N

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

9. API Well No.

30-045-32927

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

10. Field and Pool, or Exploratory Area

Basin Dakota/Blanco Mesaverde

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

NESE 2170' FSL & 660' FEL Sec. 30 T30N, R10W

11. County or Parish, State

San Juan County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☒ Other Bridge Plug Drilled
Out DHC 1914 AZ

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

10/10/06 CASING FLOWING AT 10 PSI ON 2 -3" LINES, MAKE UP 3 7/8" 4 - BLADE JUNK MILL ON TUBING, TIH AND TAG FILL AT 4780', TY BACK TO 1 LINE, RIG UP POWER SWIVEL, BREAK CIRCULATION WITH AIR MIST, CLEAN OUT TO 4800', CIRCULATE CLEAN, SHUT DOWN AIR, RIG DOWN SWIVEL, PULL ABOVE PERFS, TURN OVER TO FLOW BACK HANDS, SHUT DOWN OVERNIGHT.

10/11/06 TIH & MILL PLUG @5130'. TIH; TAG FILL @7148'; CLEAN OUT TO 7149'.

10/13/06 TIH & LAND 2 3/8" TBG @7083'. RIG DOWN MOVE OFF LOCATION

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature

Cherry Hlava

Date 10/20/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

DEC 27 2006

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE
BY *[Signature]*

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC