Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103	
<u>District I</u> Energy, Minerals and Natural Resources	March 4, 2004 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240: District II	30-039-06212	
1301 W. Grand Ave., Artesia, NM 88210 District III OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE	
1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. B-11240-88	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	OIL CONS. DIV.	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Hamilton State DICT 2	
1. Type of Well:	8. Well Number #5	
Oil Well Gas Well X Other	·	
2. Name of Operator	9. OGRID Number	
Burlington Resources Oil & Gas Company 3. Address of Operator	14538 10. Pool name or Wildcat	
P.O. Box 4289, Farmington, NM 87499-4289	Basin Fruitland Coal/ Ballard Pictured Cliffs	
4. Well Location		
	*	
Unit Letter O: 1073 feet from the South line and 1552 feet from the East line		
Section 32 Township 26N Range 7W NMPM Rio Arriba County		
11. Elevation (Show whether DR, RKB, RT, GR,	etc.)	
6859' GL	on Dete	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Oth	er Data	
	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL V	VORK ☐ ALTERING CASING ☐	
TEMPORARILY ABANDON	DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TES	ST AND	
OTHER: Commingle 🔯 OTHER:	П	
13. Describe proposed or completed operations. (Clearly state all pertinent detail	-	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
Opening District on the first the CIDD and a complete the E. Wend On I. W. H. District Office Co.		
ConocoPhillips intends to drill the CIBP and commingle the Fruitland Coal with the Pictured Cliffs formation. Install new beam balanced pump with 16 HP Kubota Engine and BHA inside the 2 7/8" casing, slim-hole, to		
optimize gas production. Please see attached procedure and wellbore diagram.		
1		
:		
I hereby certify that the information above is true and complete to the best of my know		
grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general perm	nit 🗌 or an (attached) alternative OCD-approved plan 🔲.	
SIGNATURE		
Type or print name Amanda Sanchez E-mail address sandoar@conocophillips.com Telephone No. 505-326-9700		
(This space for State use)		
APPPROVED BY TITLE SENTENCE OF & GAS INSPECTOR, DIST. A DATE MAR 0 9 2007		
APPPROVED BY TITLE TITLE SOUTH OIL & GAS INSPECTOR, DIST. ED DATE MAR 0 9 2007 Conditions of approval, if any: Obtain permission to DHC prior to initiating this work		

1



Prepared By:

Asif Bari

Date: 02/14/2007

Project Peer review/approved By:

Dennis R. Wilson Expensed Superintendent reviewed By: Lyle Ehrlich / Guy Garreston

Date: 02/19/07 Date: 02/15/2007

Objective:

The intent of this procedure is to drill the CIBP and commingle Fruitland Coal with Pictured Cliffs formation, install new beam balanced pump (B114-143-64) with 16 HP Kubota Engine and BHA inside the 2 7/8" Casing (Slim-hole) to optimize gas production on the Hamilton State 5.

Well Name:

Hamilton State 5 - DEMAND WELL - LAST PROD. DATE: Jan-31-2006

Formation:

Fruitland Coal and Pictured Cliff

API Number:

30039062120000

AIN Number: 4909102 and 4909101

County:

Rio Arriba

State: New Mexico

Location:

Section 32 - 26N - 7W - Unit O

1073 FSL and 1552 FEL

Lat: N36 26.356 and Log: W107 35.662

CIBP:

2726' 2934'

TD: Artificial Lift:

Recommend to install LUFKIN - Churchill Beam Balanced - API Size B114-143-64

Procedure:

- 1. Hold pre-job safety meeting. Comply with NMOCD, BLM, and ConocoPhillips safety and environmental regulations. Test rig anchors prior to moving in the rig.
- 2. MIRU. Note casing pressure and record in Wellview. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with SRB treated 2% KCL, if necessary.
- 3. ND Wellhead and NU BOP.
- This well currently has 2 7/8" Casing (Slim-hole) and no tubing. 4.
- 5. TIH and Drill out the CIBP = 2726' to TD = 2934' using Weatherford Rental Tools, which includes:
 - (~98) 1-13/16" OD 4.16# N-80 Drill Tubing with 1-13/16" HOMCO Flush Joint Conn.
 - (3) Drill collar slick 2" OD with 1-13/16" WFJ
 - (50) Sub, Lift plugs / Nubbins 1-13/16" OD HFJ
 - (1) Slips, Deep well 3-1/2" with 1-1/2" slips
 - (1) Clamps, Safety Type "T" with 4 segs
 - (1) Elevator, Slip type LYT with 1-1/2" slips)
 - (1) Mill, Cement / Junk 2-1/4" OD and 1-13/16" OD HFJ Box connector.
- 6. Recommended Maximum Torque Allowed for Drill Pipe = 400 ft.lbs.
- 7. If fill is present, cleanout to TD @ 2934' with air package. If unable to clean out to TD, contact Production Engineer to verify tubing landing depth.
- 8. **TOOH** with Weatherford Tools
- 9. ND BOP and NU Radigan BOP.



- 10. **TIH** as follows (setting bottom up):
 - Insert Pump Anchor set at 2880'
 - 5' Perforated Sub (0.97" ID) (0.1875" Diameter with 10 holes/ft)
 - Shear Tool (rated up to 6000 lbs. down hole and 13000 lbs. on surface)
 - 1-1/2" x 12' RWBM-Z-HVR insert pump
 - Double standing valve, single traveling valve, California pattern balls, w/ sand check,
 3' SM Grooved -.005" Plunger
 - Four 1-7/8" ID Hollow Sinker bars (20' length and 200 lbs. each)

Tubing Specifications are 1.315" OD (1.049" ID) 1.72#/ft J-55 R-2 IJ-10RD ERW **Optimum Torque Limit = 400 ft.lbs. Collapse = 10,000 psi** Internal Yield = 9,730 psi

- (~94) Joints of IJ Tubing 1.315" J-55 (1" Nom OD) (Use 1 +/- tubing joint as necessary to obtain proper landing depth and should be spaced out for 64" stroke)
- Pull Tube 1-1/2" x 18' Connector (Hollow Polished Rod) with 10' Liner
- 10" Top Pull Tube Adaptor
- 11. NU stuffing box and rod rotator.
- 12. Place 90 degrees Swivel with 1" ID Hose with winter insulator (~12' Length)
- 13. There are no short spacing joints. Install hollow polished rods on string, move string down until polished rods is at desired height, perform anchor setting sequence to set anchor, stack out string install stuffing box packing.
- 14. The pump should be spaced out exactly right to keep from shearing the shear tool and not pumping too high in the stroke by Dave Allison (COP Pumping Unit Expert) and Gary Noyes (Energy Pump and Supply).
- 15. **Note:** Do not pull more than 9,000 lbs on surface to avoid shearing the Shear Tool.
- 16. Load 1" IJ tubing and test to 1500 psi and bleed off. Then, long stroke pump 64" or less to 500 psi. **Note:** Please pump long stroke without messing pump setting and spacing.
- 17. Set the pumping unit, re-plum the wellhead and set stroke not to Tag (NO TAG!)
- 18. Verify well pumps up before moving out.
- 19. Then, notify lease operator that the well is ready to be returned to production. RDMO.
- 20. Should you have any questions or need additional info, please contact Production Engineer.

Recommended:	Approved:	·
	Asif Bari (Production Engineer)	Lyle Ehrlich (Sr. Rig Supervisor)
	Office: (505) 324-5103	Office: (505) 599-4002
	Cell: (505) 947-1822	Cell: (505) 320-2613



HAMILTON STATE 5 FRC

Unit O T026N R007W Sec.032 1073 FSL & 1552 FEL

RIO ARRIBA COUNTY, NM

API Number: 30039062120000

AIN: 4909102


Latitude N36 26.356 Longitude W107 35.662

Spud date: 4/30/54

Completion Date: 4/6/05

GL = 6,859'

KB= 0,000'



CIBP= 2726' TD= 2934'