


CHAPARRAL ENERGY
701 South Lake Blvd.
Oklahoma City, Oklahoma 73114




TO : CHARLIE T. PERRIN, DEPUTY O&G INSPECTOR NMOC
FROM : JIM HICKS, AGENT, CHAPARRAL ENERGY
SUBJECT: CHAPARRAL ENERGY
2003 REVISED BRADENHEAD TEST SCHEDULE
DATE : AUGUST 28, 2003

Please find attached revised 2003 Bradenhead Tests for Navajo Tribe AR-4, AR-6 and BU-2. The reason for these revisions is that the previous operators' field personnel had told us that the valves at surface were bradenhead valves, when in truth they were intermediate casing valves.

The wellheads of these three wells have been dug down to the surface casing and it was found that the surface casings had been 'orange peeled' and welded to the intermediate casing with no bradenhead valves. Thread-O-Lets have been welded to the surface pipes and hot tapped in order that bradenhead tests can be properly performed.

In regards to ~~Navajo Tribe BU-2, B34-26N-18W API 30-045-21812~~, reference RBDMS CTP0317563068 the bradenhead has no pressure and flows nothing and should eliminate the need for remedial action.

If you have any questions, please call me at 505/327-4902.


JIM HICKS
AGENT, CHAPARRAL ENERGY
POST OFFICE DRAWER 3307
FARMINGTON, NEW MEXICO 87499
505/327-4902

Attachments

cc: RAY VESTAL
Chaparral Energy