## submitted in lieu of Form 3160-5 **UNITED STATES** DEPARTMENT OF THE INTERIOR

**BUREAU OF LAND MANAGEMENT** 

RCVD APR26'07 OIL CONS. DIV.

DIST. 3

	Sundry Notices and Report	s on Wells 7007 APR 18 PM 4: 14		
		OFCEIVED	5.	Lease Number NMSF-078081
1.	Type of Well GAS	210 FASHINGTON HM	6.	If Indian, All. or Tribe Name
2.	Name of Operator		7.	Unit Agreement Name
	BURLINGTON RESCURCES OIL & GAS COMPANY LP			Huerfanito Unit
			8.	Well Name & Number
<ol> <li>Address &amp; Phone No. of Operator</li> <li>PO Box 4289, Farmington, NM 87499 (505) 326-9700</li> </ol>			9.	Huerfanito Unit #73 API Well No.
4	Location of Wall Factors Son T. D. M.		<del></del>	30-045-06163
4.	Location of Well, Footage, Sec., T, R, M Sec., TN, RW, NMPM		10.	Field and Pool
	Unit H (SENE) 1530' FNL & 1190' FEL, Sec. 33, T27N, R9W NMPM			Basin Dakota
			11.	County and State San Juan Co., NM
	X Subsequent Report	Abandonment Change of Plans Recompletion New Construction Plugging Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection		Install Tubing
13.	Describe Proposed or Complete	d Operations		
free 4/2. TIH RB. pres 6/4/10 & p bit. Esta circ	e. TOOH recovered tog hanger. Three 707 Latch onto fish. TIH to free point I to Model "D" pkr. RU swivel. Estal P @ 6782'. Load hole w/FW. 4/5/07 ssure off. TOOH. 4/9/07 TIH w/pkr. 328'. Establish injection rate 1.5bpm 0/07 TIH w/pkr &set @ 5867'. Apply nump cmt 9bbls @ 15.6psi. Displacer Tag tOC @ 5991'. RU swivel. Establish circulation. Drill cmt from 610 culation. 4/13/07 TOOH. LD bit. TOO	BOP. 3/30/07 Attempt to spear fish, could not spear ads parted @ 2 1/16". TIH w/overshot. Latch onto fish &cut off 2 1/16" tbg. Pull 32K while marking for strollish circulation. Latch into pkr. Circulate clean. TOC TIH w/2 3/8" tbg landed @ 6968'. ND BOP. NU BC Isolate csg leak. PT csg to 500psi from 6266'-0' & 6 a @ 1500psi. TOOH w/2 3/8" tbg. Dump 15gals sand y 500psi to annulus. PT pumps & lines to 3000psi. Est nent 26bbls. Pressure locked up 2500psi. 4/11/07 Resolish circulation. Drill cmt from 5991'-6107'. Swivel 17'-6315'. Circulate clean. PT csg to 500pso, ok. TIH DH LD RBP. TIH w/4 3/" bit to 3000'. 4/16/07 Tag (65724'. TIH w/224jts 2 3/8" tbg landed @ 6968', F-released @ 1900hrs 4/17/07.	th. Pulling 36000 retch seal assemble 4/4/07 PU 5 DP. PT to 500psi 328'-6782'. Isol I down csg on R stablish injection lease. TOOH w/ leaking. Rig rep I w/4 '4" bit tag 7000'. RU sw	OH. Release from fish. TOOH. oby. RD W/L tools. 4/3/07  1.5" RBP. TIH to 6782'. Set  1. lost 300psi in 7mins. Bleed ated csg leak between 6266'  BP. Flush w/5bbls 2% KCL.  1. rate 1.5bpm @ 1950psi. Mix  2. 3/8" tbg. LD pkr. TIH w/4 %  1. air. 4/12/07 RU new swivel.  1. sand @ 6760'. Establish ivel. Establish circulation. C/O
14	. I hereby certify that the foregoin	ng is true and correct.		
Sig	ned Amanda.	Amanda Sanchez	Title Regulat	ory Tech Date <u>3/18/07</u>
— (Т!	is space for Federal or State Office	use)	ACCE	PTED FOR RECORD
AP	PROVED BY NDITION OF APPROVAL, if any	Title		PR2 5 2007 —
Title	· · · · · · · · · · · · · · · · · · ·	nowingly and willfully to make any department or agency of	FARMIN BY 29	IGTON FIELD OFFICE

NMOCD >