

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

5. Lease Serial No.

2007 SF #077123

6. If Indian, Allottee or tribe Name

AM 11:03

7. If Unit or Agreement Name and/or No.

RECEIVED
BLM
210 FARMINGTON NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

8. Well Name and No.

Warren LS 2B

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

9. API Well No.

30-045-31969

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

10. Field and Pool, or Exploratory Area

Otero Chacra

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1105' FSL & 1095' FEL Sec. 12 T28N, R09W

11. County or Parish, State

San Juan County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐

Notice of Intent

☒

Subsequent Report

☐

Final Abandonment Notice

TYPE OF ACTION

☐

Acidize

☐

Deepen

☐

Production Resume

☐

Water shut-Off

☐

Alter Casing

☐

Fracture Treat

☐

Reclamation

☐

Well Integrity

☐

Casing Repair

☐

New Construction

☐

Recomplete

☒

Other Chacra Completion
Subsequent Sundry

☐

Change Plans

☐

Plug and Abandon

☐

Water Disposal

☐

Convert to Injection

☐

Plug Back

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

5/29/07 MIRU SU; TIH SET 2 - 2 7/8" COMPOSITE BRIDGE PLUGS @3700', (OVER MV PERFS) TEST CASING TO 5000 PSI, HELD 10 MIN. GOOD TEST. TIH with 2" GUN & PERF CHACRA @6 JSPF; 3102'-3126'; 3140'-3148'; 3222'-3252'. TOTAL SHOTS 372. RIG DN

5/31/07 TIH & FRAC CHACRA w/116,385 lbs 16/30 Brady snd. 60Q N2 FOAM. Av PRES 4001 psi. Rig DN.

6/01/07 Turn well over to production.

Tubingless. Well capable of producing from Chacra only. Test data to follow.

RCVD JUN 7 07
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature

Cherry Hlava

Date 06/01/2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

JUN 05 2007

NMOC

FARMINGTON FIELD OFFICE