

30-045-31448 formation Tops for Roosevelt SWD #1

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals, and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries);

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Ojo Alamo	Surface		
Pictured Cliffs	1272	1365	
Cliffhouse	2799	2973	
Point Lookout	3672	4010	
TD	4010		

38. GEOLOGIC MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH
Pictured Cliffs	1272	1272
Cliffhouse	2799	2799
Point Lookout	3672	3672
		.
		.
		.
		.