UNITEDSTATES 'DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

FORMAPPROVED					
OM B No 1004-0137					
Expires: March 31, 2007					

5. Lease Serial No.	
---------------------	--

Do not use this form for managed to drill, or to us enter on			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No. San Juan 29-5 Unit		
1. Type of Well Oil Well X Gas Well Other	8. Well Name and No.		
2. Nameof Operator	SAN JUAN 29-5 UNIT 35M		
ConocoPhillips Company 3a. Address 3b. PhoneNo.(include area code)	9. API Well No. 30-039-30155		
PO BOX 4289 Farmington NM 87499 (505)326-9597	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Blanco Mesaverde / Basin Dakota		
610 NORTH 755 WEST UL: D, Sec: 34, T: 29N, R: 5W	11. County or Parish, State RIO ARRIBA NM		
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, I	REPORT, OR OTHER DATA		
TYPEOF SUBMISSION TYPEOF ACTION			
Acidize Deepen Production (S Notice of Intent Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete	tart/Resume)		
Subsequent Report Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily A			
Final Abandonment Notice Convert to Injection Plug Back Water Disposa	ıl		
determined that the site is ready for final inspection.) 06/16/07 MIRU H&P #282. NU BOP - PT ok. PT casing to 600#/30min. Good to 200' to 237'. Drill 8 3/4" hole to intermediate TD @ 4080'. Circ. hole. TOOH. RIF bottom; followed with 79 jnts 7", 20#, J-55 ST&C csg on top and set @ 4068'. 0 mud, 10 bbl wtr. Pump 508 sx (1086cf - 193 bbl) Prem Lite cmt w/3% CaCL, 0.2 FL-52A, 0.4% SMS. Tail w/89 sx (118cf - 21 bbl) Type III cmt w/1% CaCL, 0.25 displace w/160 bbl wtr. Lost returns 127 bbl into displacement. Slow pump rate	H w/4jnts 7", 23#, J-55 LT&C csg on 6/22/07 RU to cmt. Preflush w/20bbl		
ok. WOC. Spacer back to surface but no cement to surface. 6/22/07 Run temp from Jim Lovato (BLM) ok to proceed - remediation not necessary. 06/22/07 PT 7" csg to 1500#/30min. Good test. Drill 6 1/4" hole to TD @ 8209'. 11.6#, J-55 LT&C csg; 129 jnts 4 1/2" 10.5#, J-55 ST&C csg; and 36 jnts 4 1/2" 8209'. RU to cmt. Preflush w/10 bbl spacer, 2 bbl wtr. Pump 313 sx (620 cf - 11 0.3% CD-32, 6.25 pps LCM1, 1% Fl-52A. Drop plug and displace w/10 bbl sugafloats ok. WOC. ND BOP. RDMO 06/24/07. Will report 4 1/2" TOC & PT on con	pps cello, 0.2% FI-52A. Drop plug and to 2 bpm. Bump plug to 1500# - floats survey. TOC @ 515'. Verbal approval 7) Circ hole. TOOH. RIH w/9 jnts 4 1/2", , 11.6#, J-55, LT&C on top & set @ 0 bbl) Prem Lite cmt w/0.25 pps cello, ar wtr, 119 bbl wtr. Bump plug to 1600# -		
ok. WOC. Spacer back to surface but no cement to surface. 6/22/07 Run temp from Jim Lovato (BLM) ok to proceed - remediation not necessary. 06/22/07 PT 7" csg to 1500#/30min. Good test. Drill 6 1/4" hole to TD @ 8209'. 11.6#, J-55 LT&C csg; 129 jnts 4 1/2" 10.5#, J-55 ST&C csg; and 36 jnts 4 1/2" 8209'. RU to cmt. Preflush w/10 bbl spacer, 2 bbl wtr. Pump 313 sx (620 cf - 11 0.3% CD-32, 6.25 pps LCM1, 1% Fl-52A. Drop plug and displace w/10 bbl sugafloats ok. WOC. ND BOP. RDMO 06/24/07. Will report 4 1/2" TOC & PT on con 14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)	pps cello, 0.2% FI-52A. Drop plug and to 2 bpm. Bump plug to 1500# - floats survey. TOC @ 515'. Verbal approval 7) Circ hole. TOOH. RIH w/9 jnts 4 1/2", , 11.6#, J-55, LT&C on top & set @ 0 bbl) Prem Lite cmt w/0.25 pps cello, ar wtr, 119 bbl wtr. Bump plug to 1600# - npletion sundry. CIL CONS. DIV.		
ok. WOC. Spacer back to surface but no cement to surface. 6/22/07 Run temp from Jim Lovato (BLM) ok to proceed - remediation not necessary. 06/22/07 PT 7" csg to 1500#/30min. Good test. Drill 6 1/4" hole to TD @ 8209'. 11.6#, J-55 LT&C csg; 129 jnts 4 1/2" 10.5#, J-55 ST&C csg; and 36 jnts 4 1/2" 8209'. RU to cmt. Preflush w/10 bbl spacer, 2 bbl wtr. Pump 313 sx (620 cf - 11 0.3% CD-32, 6.25 pps LCM1, 1% Fl-52A. Drop plug and displace w/10 bbl sugar floats ok. WOC. ND BOP. RDMO 06/24/07. Will report 4 1/2" TOC & PT on con-	pps cello, 0.2% FI-52A. Drop plug and to 2 bpm. Bump plug to 1500# - floats survey. TOC @ 515'. Verbal approval 7) Circ hole. TOOH. RIH w/9 jnts 4 1/2", , 11.6#, J-55, LT&C on top & set @ 0 bbl) Prem Lite cmt w/0.25 pps cello, ar wtr, 119 bbl wtr. Bump plug to 1600# - npletion sundry. CIL CONS. DIV.		
ok. WOC. Spacer back to surface but no cement to surface. 6/22/07 Run temp from Jim Lovato (BLM) ok to proceed - remediation not necessary. 06/22/07 PT 7" csg to 1500#/30min. Good test. Drill 6 1/4" hole to TD @ 8209'. 11.6#, J-55 LT&C csg; 129 jnts 4 1/2" 10.5#, J-55 ST&C csg; and 36 jnts 4 1/2" 8209'. RU to cmt. Preflush w/10 bbl spacer, 2 bbl wtr. Pump 313 sx (620 cf - 11 0.3% CD-32, 6.25 pps LCM1, 1% Fl-52A. Drop plug and displace w/10 bbl sugafloats ok. WOC. ND BOP. RDMO 06/24/07. Will report 4 1/2" TOC & PT on con 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	pps cello, 0.2% FI-52A. Drop plug and to 2 bpm. Bump plug to 1500# - floats survey. TOC @ 515'. Verbal approval 7) Circ hole. TOOH. RIH w/9 jnts 4 1/2", , 11.6#, J-55, LT&C on top & set @ 0 bbl) Prem Lite cmt w/0.25 pps cello, ar wtr, 119 bbl wtr. Bump plug to 1600# - npletion sundry. CIL CONS. DIV.		
ok. WOC. Spacer back to surface but no cement to surface. 6/22/07 Run temp from Jim Lovato (BLM) ok to proceed - remediation not necessary. 06/22/07 PT 7" csg to 1500#/30min. Good test. Drill 6 1/4" hole to TD @ 8209'. 11.6#, J-55 LT&C csg; 129 jnts 4 1/2" 10.5#, J-55 ST&C csg; and 36 jnts 4 1/2" 8209'. RU to cmt. Preflush w/10 bbl spacer, 2 bbl wtr. Pump 313 sx (620 cf - 11 0.3% CD-32, 6.25 pps LCM1, 1% Fl-52A. Drop plug and displace w/10 bbl sugar floats ok. WOC. ND BOP. RDMO 06/24/07. Will report 4 1/2" TOC & PT on con 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Juanita Farrell Title Regulatory Sp	pps cello, 0.2% FI-52A. Drop plug and to 2 bpm. Bump plug to 1500# - floats survey. TOC @ 515'. Verbal approval 7) Circ hole. TOOH. RIH w/9 jnts 4 1/2", , 11.6#, J-55, LT&C on top & set @ 0 bbl) Prem Lite cmt w/0.25 pps cello, ar wtr, 119 bbl wtr. Bump plug to 1600# - npletion sundry. ———————————————————————————————————		
ok. WOC. Spacer back to surface but no cement to surface. 6/22/07 Run temp from Jim Lovato (BLM) ok to proceed - remediation not necessary. 06/22/07 PT 7" csg to 1500#/30min. Good test. Drill 6 1/4" hole to TD @ 8209'. 11.6#, J-55 LT&C csg; 129 jnts 4 1/2" 10.5#, J-55 ST&C csg; and 36 jnts 4 1/2" 8209'. RU to cmt. Preflush w/10 bbl spacer, 2 bbl wtr. Pump 313 sx (620 cf - 11 0.3% CD-32, 6.25 pps LCM1, 1% Fl-52A. Drop plug and displace w/10 bbl suga floats ok. WOC. ND BOP. RDMO 06/24/07. Will report 4 1/2" TOC & PT on con 14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) Juanita Farrell Title Regulatory Sp Signature Date 06/28/2007	pps cello, 0.2% FI-52A. Drop plug and to 2 bpm. Bump plug to 1500# - floats survey. TOC @ 515'. Verbal approval 7) Circ hole. TOOH. RIH w/9 jnts 4 1/2", , 11.6#, J-55, LT&C on top & set @ 0 bbl) Prem Lite cmt w/0.25 pps cello, ar wtr, 119 bbl wtr. Bump plug to 1600# - npletion sundry. RCUD JUL 2"07 OIL CONS. DIV. ecialist DIST. 3		

(Instructions on page 2)