UNITED STATES		5. Lease NMNM-03551
DEPARTMENT OF THE INTERIOR		
BUREAU OF LAND MANAGEMENT RECEIV		N/FD
1,		6. If Indian, Allottee or Tribe Name
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different		7. Unit Agreement Name
reservoir. Use "APPLICATION FOR PERMIT" for such proposals)		
1. Oil Well [] Gas Well [] Other []		8. Well Name and No.
GAS WELL		BREECH "E" 118
		9. API Well No.
Caulkins Oil Company 3. Address of Operator: (505) (22, 1544)		30-039-06670-00S1 10. Field and Pool, Exploratory Area
(505) 632-1544		
P.O. Box 340, Bloomfield, NM 87413 4. Location of Well (Footage, Sec., Twp., Rge.)		BASIN DAKOTA 11. Country or Parish, State
1190' F/S 1850' F/W SEC. 1-26N-6W		Rio Arriba Co., New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION		
[X] Notice of Intent	[] Abandonment	[] Change of Plans
	[]Recompletion	[] New Construction
[] Subsequent Report	[] Plugging Back	[] Non-Routine Fracturing
[] Final Abandonment Notice	[X] Casing Repair Altering Casing	[] Water Shut-Off [] Conversion to Injection
[] I mai Abandonnient Notice	Other	Dispose Water
17. Describe Proposed or Completed Operations:		
9-2-03 Rigged up.		
T. O. H. with tubing.		7 2003
T. O. H. with tubing. T. I. H. with retrievable bridge plug and packer. Set retrievable bridge plug at 3941', set packer and tested plug, OK.		
T. O. H. with tubing. T. I. H. with retrievable bridge plug and packer.		
Pulled up hole with packer searching for leak in casing.		
Isolated hole in casing at 2490'.		EC [2.03.0] When
T. O. H. with packer.		
9-3-03 Received verbal approval from Wayne Townsend with BLM to repair casing leak at 2490' and to cement to surface behind pipe by the following procedure:		
Run bond log to determine top of cement.		
Perforate at top of existing cement and above hole at 2490'.		
Circulate cement up outside of pipe and squeeze holes at 2490'.		
Then perforate and cement as necessary to circulate cement to surface through bradenhead.		
Then perforate and coment as necessary to encurate coment to surface unough bradelinead.		
NOTE: The format is issued in lieu of U.S. BLM Form 3160-5		
18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT		
SIGNED: Ment 7 Vergue TITLE: Superintendent DATE: September 24, 2003 ROBERT L. VERQUER		
APPROVED BY: TITLE: DATE:		
CONDITIONS OF APPROVAL, IF ANY		
,		