In Lieu of "

## UNITED STATES

Form 316 (June 199	20)	ENT OF INTERIOR AND MANAGEMENT		Budget Bureau No 1004-0135 . Expires: March 31, 1993	
Do not t	SUNDRY NOTICE AND use this form for proposals to drill or to deepen of TO DRILL" for perm	r reentry to a different reservoir. Use "APPLICATION	SEIVED	Cas 217 esignation and Serial No. NMSF-078768  If Indian, Allottee or Tribe Name	
	SUBMIT IN T	RIPLICATE .	7.	If Unit or CA, Agreement Designation	
l. Type of Well Oil Well X Gas Well Other		8	Well Name and No. ROSA UNIT #344A		
Name of Operator     WILLIAMS PRODUCTION COMPANY		9	API Well No 30-039-30151		
3.	3. Address and Telephone No PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10	Field and Pool, or Exploratory Area BASIN FRUITLAND COAL	
4	Location of Well (Footage, Sec , T., R , M , or 660' FSL & 1940' FEL, SW/4 SE/4 SEC 25	• *	11.	County or Parish, State RIO ARRIBA, NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
	TYPE OF SUBMISSION T		E OF ACTION		
	Notice of Intent  X Subsequent Report  Final Abandonment	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other <u>Complete</u>		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*					
07-17-2007 MIRU, ND WH, NU BOP stack, RU rig floor & tongs, NU blooie lines & manifold. Test 7" csg integrity & BOP's to 250 psi low & 1500 psi high for 15 min, good test. PU, MU & TIH as follows; 6 1/4" RR button bit, bit sub w/ float & crows foot, 8 4 3/4" DC's, X-over sub, 93 jts 2 7/8" AOH DP. Secure well & location, SDON.					
07-18-2007 Tie back, PU 3.5 PS, PU DP jt 94, tag cmt @ 3197'. Break circ w/ produced coal water. Drill float collar @ 3205' & guide shoe @ 3252', DO open hole to 3390'. Circ bottoms up, LD 5 jts DP, hang back PS, SDON.					
07-19-2007 SIP 150#, bleed well down @ 2" line. PU 6 jts DP, Tag @ 3390', break circ w/ produced coal water begin drill out. <b>TD well @ 3433'</b> . Circ well bottoms up. Drop Totco survey tool @ 3433'. LD 8 jts DP, broke chain on rig, repair chain. POH & standback 94 jts DP & 8 DC's, recover survey F/3433' = 2-1/4 degree deviation. SM w/ rig crew & Halliburton logging. RU HLS, Run mechanical log, RD HLS. Secure well & location, no accidents reported. SDFN					
		Continued on Back		OIL CONS. DIV.	
				DIST, 3	
14.	I hereby certify that the foregoing is true and co	orrect		a state of the sta	
	Signed Nacy Coso Tracy Ross	Title Sr. Production Analyst Da	ate <u>Au</u>	igust 27, 2007CEPTED FOR ACCORD	
	(This space for Federal or State office use)			AUG 2 8 2007	
	Approved by	Title	Da	ate FARMINGTONFIELD OFFICE	
	Conditions of approval, if any:				