

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

RECEIVED

OCT 16 2007

Bureau of Land Management  
Farmington Field Office

1. Type of Well  
GAS

2. Name of Operator  
CDX RIO, LLC

3. Address & Phone No. of Operator

2010 Afton Place, Farmington, New Mexico 87401 (505) 326-3003

4. Location of Well, Footage, Sec., T, R, M

660' FSL, 2100' FWL, Sec. 24, T-26-N, R-5-W, NMPM

NSL-5291, DHC-2130az

5. Lease Number  
Jicarilla Contract 108  
6. If Indian, All. or  
Tribe Name  
Jicarilla Apache  
7. Unit Agreement Name

8. Well Name & Number

Jicarilla C #4F  
9. API Well No.

30-039-29590

10. Field and Pool

Blanco MV/Basin DK  
11. County and State

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

| Type of Submission                                   | Type of Action  |
|--|---|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Abandonment <input type="checkbox"/> Change of Plans                           |
| <input type="checkbox"/> Subsequent Report           | <input type="checkbox"/> Recompletion <input type="checkbox"/> New Construction                         |
| <input type="checkbox"/> Final Abandonment           | <input type="checkbox"/> Plugging <input type="checkbox"/> Non-Routine Fracturing                       |
|  | <input type="checkbox"/> Casing Repair <input type="checkbox"/> Water Shut off                          |
|  | <input type="checkbox"/> Altering Casing <input type="checkbox"/> Conversion to Injection               |
|  | <input checked="" type="checkbox"/> Other <input type="checkbox"/> Permanently abandon Dakota Formation |

RCVD OCT 17 '07  
OIL CONS. DIV.  
DIST. 3

13. Describe Proposed or Completed Operations

1. MOL. RU.
  2. Kill well with 2% KCl water.
  3. TOOH with tubing.
  4. RU 7" lubricator.
  5. RIH with 4.5" wireline gauge ring to 6750'.
  6. RIH and set 4.5" wireline CIBP at 6750'.
  7. Plug #1 with CIBP at 6750', dump bail 4 sx Type II cement above CIBP to 6700' to cover the Dakota perforations, top and fish at 6770' - 6893'.
  8. RIH and set 4.5" wireline CIBP at 6317'.
  9. Plug #2 with CIBP at 6317', dump bail 4 sx Type II cement above CIBP to 6267' to cover the Gallup top.
  10. Land 158 joints 2.375" 4.7# J-55 EUE tubing at 5116' (SN @ 5115'). ND BOP. NU WH. RD.
- (Verbal approval to permanently abandon Dakota from Jim Lovato, BLM on 10-11-07)

Well will continue to produce as a Mesaverde single well.

14. I hereby certify that the foregoing is true and correct.

Signed Nancy Oltmanns Title Agent Date 10-11-07

(This space for Federal or State Office use)

APPROVED BY [Signature] Title Petr. Eng. Date 10/16/07  
CONDITION OF APPROVAL, if any:

NMUCD