Submit 3 Copies To Appropriate District Office **DISTRICT I** P.O. Box 1980, Hobbs, NM 88240

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

## OIL CONSERVATION DIVISION

2040 South Pacheco Santa Fe, NM 87505 WELL API NO. 30-045-34250

**DISTRICT II** 

811 South First, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

☐ FEE State Oil & Gas Lease No. 17036

Indicate Type of Lease

STATE

Lease Name or Unit Agreement SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH .

**PROPOSALS** 

**RCVD NOV 29'07** 

ROSA UNIT COM DIL CONS. DIV.

1. Type of Well:

Oil Well Name of Operator Gas Well

Other

DIST. 3

WILLIAMS PRODUCTION COMPANY

Address of Operator

Pool name or Wildcat

P O BOX 3102, MS 25-2, TULSA, OK 74101

BASIN FRUITLAND COAL

Well Location (Surface)

Unit letter <u>J</u>: <u>1525</u> feet from the <u>SOUTH</u> line & <u>2190</u> feet from the <u>EAST</u> line Sec 33-32N-06W SAN JUAN, NM

10. Elevation (Show whether DF, RKB, RT, GR, etc.

6326' GR

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL

PLUG AND ABANDON

REMEDIAL WORK

ALTERING CASING

WORK

OTHER:

TEMPORARILY ABANDON

CHANGE PLANS

COMMENCE DRILLING OPNS.

PLUG AND **ABANDONMENT** 

PULL OR ALTER CASING

CASING TEST AND CEMENT JOB

OTHER: Completion

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

11-12-2007 MIRU, NDWH & NUBOP stack, finish spotting in equip, RU pump, pit & hardlines, pressure test 7" csg & blind rams to 1500 psi for 30 mins w/ no leak off, RU rig floor, drain up pump & lines & SWIFN.

11-13-2007 MU 6 1/4" bit, tally & caliper eight 4 1/4" DC's, tally, rabbit & TIH w/ 95 jts 2 7/8" DP & tag cmt @ 3200', psi test pipe rams & csg @ 1500 psi w/ no leak off, RU 3.5" PS & break circ w/ rig pump, DO 16' of cmt to FC @ 3216', DO 23' shoe it to 3239', DO open hole (104') to 3343', well started taking wtr @ top coal seam & continued taking 30 bph thru out open hole drlg, circ well clean, LD 4 its DP & set bit in 7" csg, drain up pump & lines, SWIFN.

Continued on Back I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE: SR. Production Analyst SIGNATURE DATE: November 26, 2007 Type or print name Telephone No: \_(918) 573-6254 (This space for State use)

**APPROVED** BY

Deputy Oil & Gas Inspector, District #3 TITLE

Conditions of approval, if any:

11-14-2007 TIH w/ 4 jts & set bit @ 3330', break circ w/ rig pump, well took 56 bbls produced wtr to load, tag up @ 3343', DO 107' of open hole to 3450' (TD), circ bottoms up, cont to loose 35 bph wtr, LD 1 jt DP, TOH w/ bit, MU 9.5" Baker under reamer w/ shock sub & TIH w/ DC's & DP, set UR @ shoe, RU 3.5" PS, drain up pumps & lines, SWIFN.

11-15-2007 Pressure test lines & unload wtr off well @ 750 psi, SU 12 bph a/s mist & UR open hole from 3250' to 3450', circ well clean & blow well dry, LD 7 jts & pull UR into 7" csg, RD 3 ½" PS, change over to 2 lines, TOH w/ UR & LD DP & DC's in pipe basket, BO & LO tools, RD all KOT rental equip & prepare to release, ND HCR stack & upper BOP's. SDFN.

11-16-2007 SICP = 190 psi, finish NUBOP & ND blooie line, blow well down, tally, rabbit & TIH w/ production string, land 2-7/8" tbg @ 3236' as follows, one 2.875, EUE 1/2 M/S, one 2.28" EUE S/N, 98 jts 2.875", 6.5#, J-55, EUE 8rnd tbg, RD rig floor, NDBOP stack & NUWH & test, RD rig & surface equip, turn well to production department, release rig @ 1600 hrs, 11/16/07.

NOTE: Due to BLM closure, we will be unable to finish the cavitation on this well. A rig will be moved on this location on or about April 1<sup>st</sup>, 2008 to finish the completion operations on this well.