NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe. New Mexico

(Form C-104)
Revised 7/1/57

REQUEST FOR (OIL) - (GAS) ALLOWABLE

New Well Recompletion

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-101 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

				•				Apri]			
					(Pla		•••••	•		(Date)	•
NE ARE	HERE	BYRE	QUESTI	NG AN ALLOWABL	E FOR A WEI	LL KNOWN	AS:				
manag	ing a	gent,	Tenneco	NG AN ALLOWARD thru Allen Da 0011 Co. Unit "	A W	ell No1	in	NW	1/4	NW	1/4
D Unit	Lotter	, Sec	1	, T. 29N , R	12W , NMP	'M.,	Basin Dako	ota	·····	•••••	.Poo
•		ı		County. Date Spud	dad 3-12-6	T Det	e Drilling C	hata[nm	5	10_61	
		licate lo		Elevation 5906						6750 6750	
Pie	ase ind	icate lo	cauon:	Top Oil/Gas Pay6					Dakot		
D	C	В	A			Tune of 1100				-	
х				PRODUCING INTERVAL -		4) 6	٠.	1962			
E 1	F	G	Н	Perforations 6689-	·93; 6700-06	; 6714-18;	6605-20	; 6527	333; (<u> </u>	24
	•	· u		Open Hole	·	Casing Shoe_	6785	Depta Tubin	<u>6</u> 6	515	
				OIL WELL TEST -					\$2. 6~v	-41	
L	K	J	I					•		<u> </u>	hoke
	ŀ		1.	Natural Prod. Test:_		• .					
M	N	0	P	Test After Acid or F	racture Treatmen	t (after recov	ery of volum	e of oil	equal t	o voเป็นไท	e of
*		U	•	load oil used):	bbls.oil, _	bbls	water in	hrs, _	min	Size	
	ì			GAS WELL TEST -					Ü	1	
ubling "G		nd Gemen	ting Recor	3 11	itot, back press	ure, etc.):					
Size	F	eet	Sax		itot, back press racture Treatmen	ure, etc.): t:2882	MCF,				
Size		eet	_	Method of Testing (p Test After Acid or F Choke Size 3/4	itot, back presso racture Treatmen Method of Testind	ure, etc.): t: 2882 g: Flowi	mcF,	/Day; Hou	rs flow	ed <u>2</u> 1	+
Size 3-5/8	F	3	Sax	Method of Testing (p Test After Acid or F Choke Size 3/14 Acid or Fracture Tree	itot, back pressi racture Treatmen Method of Testing atment (Give amou	t: 2882 g: Flowi	MCF,	/Day; Hou	rs flow	ed <u>2</u> 1	+
Size 3-5/8 -1/2	25 <u>5</u>	3	Sax 200	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Trees	itot, back pressing racture Treatment Method of Testing atment (Give amount 1 water 93.0	t: 2882 g: Flowi	MCF, ng als used, suc	/Day; Hou	rs flow	ed <u>2</u> 1	+
Size 3-5/8 -1/2	25 <u>5</u>	74	Sax 200	Method of Testing (p Test After Acid or F Choke Size 3/14 Acid or Fracture Tree	itot, back pressing racture Treatment Method of Testing atment (Give amount 1 water 93.0	t: 2882 g: Flowi	MCF, ng als used, suc	/Day; Hou	rs flow	ed <u>2</u> 1	+
-5/8 -1/2	253 677	74	Sax 200	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Treasand): 140,000 ga Casing Tubi Press. 710 Pres Cil Transporter	itot, back pressing the property of the proper	t: 2882 g: Flowi unts of materio 000 lbs 20 e first new run to tanks	mg als used, suc -40 sd 5-30-61	/Day; Hou	rs flow	ed <u>2</u> 1	+
-5/8 -1/2	253 677	74	Sax 200	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Treasand): 140,000 ga Casing Tubi Press. 710 Pres Cil Transporter	itot, back pressing the property of the proper	t: 2882 g: Flowi unts of materio 000 lbs 20 e first new run to tanks	mg als used, suc -40 sd 5-30-61	/Day; Hou	rs flow	ed 2 ¹	and
-5/8 -1/2 -3/8	253 677 650	3 7 ¹ 4	Sax 200	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Treasend): 140,000 gal Casing Tub: Press. 710 Press.	itot, back pressi racture Treatmen Method of Testine etment (Give amou 1 water 93,0 ing 230 Date ss. 230 cil Plateau, Inc	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks 2. ural Gas C	mg als used, suc -40 sd 5-30-61	/Day; Hou	rs flow	ed 2 ¹	and
Size 3-5/8 -1/2 -3/8	253 677 650	3 7 ¹ 4	Sax 200	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Trea sand):140,000 ga. Casing Tub. Press. 710 Press. Cil Transporter Gas Transporter	itot, back pressi racture Treatmen Method of Testine etment (Give amou 1 water 93,0 ing 230 Date ss. 230 cil Plateau, Inc	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks 2. ural Gas C	mg als used, suc -40 sd 5-30-61	/Day; Hou	rs flow	ed 2 ¹ r, oil,	and 2002
Size 3-5/8 -1/2 -3/8	253 677 650	3 7 ¹ 4	Sax 200	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Trea sand):140,000 ga. Casing Tub. Press. 710 Press. Cil Transporter Gas Transporter	itot, back pressi racture Treatmen Method of Testine etment (Give amou 1 water 93,0 ing 230 Date ss. 230 cil Plateau, Inc	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks 2. ural Gas C	mg als used, suc -40 sd 5-30-61	/Day; Hou	rs flow	ed 2 ¹ r, oil, 271	and 962
-5/8 -1/2 -3/8	677 650	7 ¹ 4	200 300	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Treesand): 140,000 ga. Casing Tub: Press. 710 Pres Gas Transporter Gas Transporter	itot, back pressing racture Treatment Method of Testing atment (Give amount water 93,0 ing Date oil Plateau, Ing El Paso Natu	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks c. ural Gas C	mcF, ng als used, suc -40 sd 5-30-61 ompany	/Day; Hou	rs flow	ed 2 ¹ r, oil,	and 962
-5/8 -1/2 -3/8 marks:	677 650	74 D4	Sax 200 300	Test After Acid or F Choke Size 3/4 Acid or Fracture Treasand): 140,000 ga. Casing Tub: Press. 710 Pres Gas Transporter Gas Transporter	itot, back pressing racture Treatment (Give amount of Water 93,0 and parts of Plateau, Inc. El Paso Natural Plateau, Treatment (Give amount of Plateau)	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks c. ural Gas C	mcF, ng als used, suc 40 sd 5-30-61 ompany	/Day; Hou	APR	ed 2	and 962
5-5/8 -1/2 -3/8 marks:	677 650	74 D4	Sax 200 300	Method of Testing (p Test After Acid or F Choke Size 3/4 Acid or Fracture Treesand): 140,000 ga. Casing Tub: Press. 710 Pres Gas Transporter Gas Transporter	itot, back pressing racture Treatment (Give amount of Water 93,0 and parts of Plateau, Inc. El Paso Natural Plateau, Treatment (Give amount of Plateau)	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks c. ural Gas C	mcF, ng als used, suc 40 sd 5-30-61 ompany t of my know acting b	/Day; Hou	APR	ed 2	and 962
-5/8 -1/2 -3/8 marks:	677 650	74 D4 tify that	200 300 t the info	Test After Acid or F Choke Size_3/4 Acid or Fracture Treasand):140,000 ga. Casing 710 Pres Cil Transporter Gas Transporter rmation given above is R. 7.0. 1962	itot, back pressing racture Treatment Method of Testing etment (Give amout I water 93,0 and plateau, Inc. Plateau, Inc. El Paso Natural et rue and comp. Tenne 62 mans	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks c. ural Gas C	mcF, ng als used, suc 40 sd 5-30-61 ompany	wledge.	APR	ed 2	and 962
5.5/8 -1/2 -3/8 marks:	677 650	74 D4 tify that	200 300 t the info	Test After Acid or F Choke Size 3/4 Acid or Fracture Treasand): 140,000 ga. Casing Tub: Press. 710 Pres Gas Transporter Gas Transporter	itot, back pressing racture Treatment (Give amount of Water 93,0 and parts of Plateau, Inc. El Paso Natural Plateau, Treatment (Give amount of Plateau)	t: 2882 g: Flowi unts of materia 000 lbs 20 e first new run to tanks c. ural Gas C	mcF, ng als used, suc 40 sd 5-30-61 ompany t of my know acting b	wledge.	APR	ed 2	and 962
5.5/8 -1/2 -3/8 marks:	677 650	74 D4 tify that	200 300 t the info	Test After Acid or F Choke Size_3/4 Acid or Fracture Treasand):140,000 ga. Casing 710 Pres Cil Transporter Gas Transporter rmation given above is R. 7.0. 1962	itot, back pressive racture Treatment (Give amount Water 93,0 in pate ss. 230 in plateau, Inc. El Paso Natural	t: 2882 g: Flowi unts of materi 000 lbs 20 e first new run to tanks ural Gas C	mcF, ng als used, suc -40 sd 5-30-61 ompany t of my know acting b t, Tenned company of O	wledge. by & th co. Oil. perator)	APROLL COmpa	ed 2	and 962
5-5/8 -1/2 -3/8 -marks:	677 650	74 D4 tify that	200 300 t the info	Test After Acid or F Choke Size_3/4 Acid or Fracture Treasand):140,000 ga. Casing 710 Pres Cil Transporter Gas Transporter rmation given above is R. 7.0. 1962	itot, back pressive racture Treatment (Give amount Water 93,0 in pate ss. 230 in plateau, Inc. El Paso Natural	t: 2882 g: Flowi unts of materic 000 lbs 20 e first new run to tanks_ c. ural Gas C	mcF, ng als used, suc -40 sd 5-30-61 ompany t of my know acting b t, Tenned company of O	wledge. by & the condition of the condit	APROLL COmpa	ed 2	and 962
Sire 3-5/8 -1/2 -3/8 marks: I here oproved.	677 650 eby cert	tify that	Sax 200 300 the information API VATION	Test After Acid or F Choke Size_3/4 Acid or Fracture Treasand):140,000 ga. Casing 710 Pres Cil Transporter Gas Transporter rmation given above is R. 7.0. 1962	itot, back pressive racture Treatment (Give amount of Testing atment (Give amount of Testing of Tes	ure, etc.): t: 2882 g: Flowi unts of materic 000 lbs 20 e first new run to tanks ural Gas C ural Gas C elete to the beseco Corp. aging agen istrict Pr Send Comm	mcF, ng als used, suc -40 sd 5-30-61 ompany t of my know acting b t, Tenned company oduction unications r	wledge. by & the condition of the condit	APROLL COmpa	ed 2	and 962
Sirr 3-5/8 1/2 2-3/8 emarks: I here oproved.	677 650 eby cert	tify that	Sax 200 300 the information API VATION	Test After Acid or F Choke Size 3/4 Acid or Fracture Treason): 140,000 ga. Casing 710 Preson Tubi Press 710 Preson Tubi Cas Transporter Gas Transporter Transporter	itot, back pressive racture Treatment (Give amount of Testing atment (Give amount of Testing of Tes	t: 2882 g: Flowi unts of materic 000 lbs 20 e first new run to tanks_ c. ural Gas C	mcF, ng als used, suc -40 sd 5-30-61 ompany t of my know acting b t, Tenned company oduction unications r	wledge. by & the condition of the condit	APROLL COmpa	ed 2	and 962