Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

	\		
FORM APPROVED			
Budget Bureau No. 1004-0135			
Fynires: M	ferch 31 1993		

FURINI APPRUVED				
udget Bur	eau No.	1004-01	35	
Expires:	March	31, 1993		

Do not use this form for proposals to o	AND REPORTS ON WELLS drill or to deepen or reentry to a different reservoir. FOR PERMIT - " for such proposals	SF-076337
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Sas Well Other 2. Name of Operator Amoco Production Company 3. Address and Telephone No. P.O. Box 800, Denver, Colorado 80201 4. Location of Well (Footage, Sec., T., R., M., or Survey Desc		8. Well Name and No. Heath Gas Com /P/ 1 8. API Well No. 3004523941 10. Field and Pool, or Exploratory Area Basin Dakota Gas 11. County or Perish, State
870' FSL 790' FWL 12. CHECK APPROPRIATE B TYPE OF SUBMISSION	Sec. 31 T 30N R 9W SE/4 SW/4 OX(s) TO INDICATE NATURE OF NOTICE , F	San Juan New Mexico
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Beck Casing Repair Altering Casing Other Cathodic Protection Well (Note: Rep	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water ort results of multiple completion on Well Completion or tion Report and Log form.)
subsurface locations and measured and true vertical depi	all pertinent details, and give pertinent dates, including estimated date of startin ths for all markers and zones pertinent to this work.]* The content of	<u>~</u> •
Please contact Patty Haefele (303) 8	DECEIV MAR - 0 199	5 5
	OLL GON. [I Dist. 3	DIV.
14.1 hereby certify that the foregoing is true and correct Signed Patty Alfel	€ Title Business Ass	sociate 02-ე2-1995
Approved by Conditions of approval, if any:	Title	APPROVED Date MAR 0 8 1995 DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or

representations as to any matter within its jurisdiction.

Ground Bed Abandonment Procedures

Well Name: Heath Gas Com P-1

Location: N31-31N-9W

- 1. Weld 6" dia. spool with diverter line to pit
- 2. MIRU
- 3. Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free. Wash hole to 300' (or TD).
- 4. Pump adequate cement to partially fill hole. Pull out work string.
- 5. Top off hole with cement. Set flexible pipline marker as PxA marker.
- 6. RDMO

Ground Bed Specifications

TD: 300' (approx) Hole Dia.: unknown Casing Dia.: unknown

Casing Length:

unknown

1/6/95 mdr

DECEIVED MAR - 9 1995 OIL CON. DIV. DIST. 3