UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

IVED

RCVD MAY 16 '08 OIL CONS. DIV. DIST. 3

MAY 1 4 2008

	Sundry Notices and Reports on Wells		
	Sureau of Land Managerr		
	Farmington Field Office	5.	Lease Number NM-9037
1	Type of Well	6.	If Indian, All. or
1.	GAS	0.	Tribe Name
	UAS		Tribe Name
		7.	Unit Agreement Name
2	Name of Operator	7.	Omt Agreement Name
2.	Name of Operator		
	BURLINGTON		
	RESOURCES OIL & GAS COMPANY LP		
		 8.	Well Name & Number
3.	Address & Phone No. of Operator		Reese Mesa 8 POW
	P.O. Box 4289, Farmington, NM 87499	9.	API Well No.
-			
			30-045-25992
4.	Location of Well, Footage, Sec., T, R, M		
		10.	Field and Pool
	Unit L (NWSW), 1660' FSL & 835' FWL, Section 12, T32N, R08W, NMPM		Basin Fruitland Coal
			Albino Pictured Cliffs
		11.	County and State
			San Juan Co., NM
	Type of Submission Type of Action X Notice of Intent Abandonment Change of Plans Recompletion New Construction Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	C Other - MIT	
	Describe Proposed or Completed Operations rlington Resources wishes to perform a required MIT for this Pressure Observation Well	per attached	procedures.
Sig — (TI AP	I hereby certify that the foregoing is true and correct. Tamra Sessions Title Regulatory Title Regulatory This space for Federal or State Office use PROVED BY Original Signed: Stephen Mason Title	Technician	Date <u>5/14/2008</u> . MAY 1 5 2008 Date
CC	NDITION OF APPROVAL, if any:		_
Title	18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of inted States any talse, fictitious or fraudulent statements or representations as to any matter within its jurisdiction	_	
1110 L	Could DOT 74 11- 110 for the Williams Surveyor The Williams Surveyor	5 Mit.	
	// Da / // / L // these	/ /TL' '	

ConocoPhillips

Reese Mesa Unit 8 (FC)

Tubing String Removal/ MIT with Coil Tubing

Lat 36° 59.685′ N **Long** 107° 37.92′ W

Prepared By:

Dryonis Pertuso

Date: 04/11/2008

BAE Peer review/approved By: Dennis Wilson

Date: xx/xx/2008

Scope of work: The intent of this procedure to pull and lay down the 1 1/4" tubing string, Rig down the work-over rig, Rig up a coil tubing unit, to perform and MIT on the 2 7/8" casing with a coil tubing packer and leave the wellbore without tubing and ready to be tested every 5 years as per BLM/ NMOCD requirement without using a work-over rig.

Est. Cost:

\$55 K

Est. Rig Days:

4 work-over rig and 1 day for the coil tubing unit

WELL DATA:

API:

30-045-259920000

Location:

1660' FSL & 835' FEL, Unit O, Section 012- T32N - R008W

PBTD:

3.784' **TD:** 4.050'

Perforations: 3,670'-3,697' (Fruitland), 3,824'-3,966' Picture Cliff (temporary abandoned)

Well History: This well was designated as a pressure observation well since December 1999. In August 1988, the well was recompleted in the Fruitland coal, but never produced in commercial quantities. In order to be able to maintain the status of this well as a pressure observation well (POW) the casing integrity must be tested every 5 years and according to the files the last test on this well was performed on July

2002.

B2 Adapters are required on all wells other than pumping wells.

Artificial lift on well (type): N/A

Est. Reservoir Pressure (psig): 100psi

Well Failure Date: N/A, last MIT on July 2002.

Current Rate (Mcfd): 0 Est. Rate Post Remedial (Mcfd): 0

Earthen Pit Required:

NO

Special Requirements:

2 hour chart for MIT, packer for a 2 7/8" 6.5# N-80 casing on a

1 1/4" coil tubing, 2 7/8" master valve, change-over flange for BOP's.

BAE Production Engineer: Dryonis Pertuso, Office: (505) 559-3409, Cell: (505) 320-6568

BAE Backup:

Jim Arroyo, Office: (505) 599-3477, Cell: (505) 320-2568

MSO:

Roger Persson

Cell: (505) 793-4426

<u>Lead:</u>

Howard Self

Cell: (505) 320-249

Area Foreman:

Mark Poulson

Cell: (505)320-2523

ConocoPhillips

Reese Mesa Unit 8 (FC) Tubing String Removal/ MIT with Coil Tubing

Lat 36° 59.685′ N **Long** 107° 37.925 W

PROCEDURE:

- 1. Hold safety meeting. Comply with all NMOCD, BLM, and ConocoPhillips safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU. Check casing, tubing, and bradenhead pressures and record them in Wellview. RU blow lines from casing valves and begin blowing down casing pressure. Load well with 2% KCl if necessary. ND wellhead pull 1 ¼" tubing slips, NU BOP.
- 3. TOOH and lay down tubing (detail below). Tubing is currently landed @ 3,684'.

From top to bottom

(112 jts) IJ 1 1/4" 2.33# J-55 tubing

- (1) 1 1/4" X 1.380" ID Seat Nipple set @ 3,650'
- (1) IJ 1 1/4" 2.33# J-55 tubing joint'
- 4. Laid down 1 ¼" tubing is to be sent to Tube scope yard.
- 5. N/D BOP's and install 2 7/8" master valve (wellhead)
- 6. RDMO Workover Rig and release from location and notify the Production Engineer and Rig Superintendent that work is completed

END OF RIG WORK - START OF COIL TUBING HDI INSTALL

- 7. Notify NMOCD 48 hours before rigging up on well.
- 8. Sanjel CTU will hold pre-job safety meeting. Comply with all NMOCD, BLM, and ConocoPhillips safety and environmental regulations.
- 9. MIRU Sanjel 1 1/4" coiled tubing unit. Check for full opening valves for tubing access. Check casing pressure and record them in Wellview.
- 10. Pick up and RIH with packer for 2 7/8" 6.5# N-80 casing on the 1 1/4" coil tubing, set packer 50' above the top perfs @ 3,670'.
- 11. Spot and RU Sanjel's mobile water tank, and load well with 2% kcl through the back side, in order to perform the MIT on the 2 7/8" casing (Casing coil tubing annulus' capacity is 0.00482 bbl/ft), approximately 18 bbls of fluid are required to load the back side.
- 12. Pressure test the casing to 500 psi for 30 min, record test on a 2 hour chart (if MIT fails, please contact production engineer).

- 13. Unset packer and blow well dry with the coil tubing unit (using air package)
- 14. RDMO 1 ¼" coiled tubing unit and ND BOP. N/U and leave closed the 2 7/8" master valve
- 15. Notify lease operator that operation is complete. RDMO.

Recommended	Dryon is Pertuso	Approved		
BAE Engineer	Dryonis Pertuso	Expense Supervisor	Stand Terwilliger	
Office	(505) 324-5158	Office	(505) 326-9582	
Cell	(505) 320-3753	Cell	(505) 320-4785	

Current Schematic ConocoPhillips Well Name: REESE MESA #8 Strace Legal Location State/Proutace NMPM,012-032N-008W BASIN (FRUTTLAND COAD 3004525992 NEW MEXICO Original Kill Elevation (f) Ground Eleuation (f) 7,040.00 KB-Ground Distance (f) KB-Caslig Flange Distance (1) kB-Tiblig Haiger Distance (1): 👙 12.00 7,052 00 7,052.00 7,052.00 Well Config 30045259920000,4/1,1/2008 9:32:46 AM (MD) 0 12 Surface Casing Cement, 12-321, 8/29/1984, 319 Cemented w/ 245 sx Class B cement: Circulated 10 bbls cement to surface. Surface, 8 5/8in, 24.00lbs/ft, K-55, 12 ftKB, 321 321 ftKB 322 IJ Tubing, 1.660in, 2.33lbs/ft, J-55, 12 ftKB, 3,650 ftKB 2,455 Ojo Alamo, 2,455 3,465 Kirtland, 3,465 3,650 Seat Nipple, 1.660in, 2.33lbs/ft, J-55, 3,650 ftkB, 3,651 ftkB 3,651 IJ Tubing, 1.660in, 2.33lbs/ft, J-55, 3,670 3,651 ftKB, 3,684 ftKB Fruitland Coal, 3,670-3,697, 8/16/1988 3,684 RATHOLE: 87' below bottom 3,697 perforation 3,784 PBTD, 3,784 Bridge Plug - Permanent, 3,784-3,789 3,789 3,821 Fruitland Coal, 3,821 3,824 Hydraulic Fracture, 11/8/1984, Frac'd w/ 50,155 gals slickwater; Pictured Cliffs, 3,824-3,966, 11/8/1984 25,000# 20/40 sand. 3,966 4,034 Production Casing Cement, 1,900-4,040, 9/4/1984, Cemented w/ 450 sx Class B 50/50 4,039 poz followed by 75 sx Class B cement TOC @ 1900' (TS) Production, 2 7/8in, 6.50lbs/ft, N-80, 12 ftKB, 4,040 4,040 ftKB TD, 4,050 4,050 Report Printed: 4/11/2008