

## NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON** 

Governor

Joanna Prukop Cabinet Secretary

Mark E. Fesmire, P.E. Director

Oil Conservation Division

\*Response Required - Deadline Enclosed\*

化的线性 医高型性医皮肤 排除者的复数 The state with the state of

02-Jul-08

BURLINGTON RESOURCES OIL & GAS COMPANY LP

PO BOX 4289

Farmington NM 87499-

NOTICE of Failed **Mechanical Integrity** 

## Dear Operator:

The bradenhead test(s) reported on the following well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by you and/or an OCD Compliance Officer employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the full nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so a Compliance Officer may witness the test.

## MECHANICAL INTEGRITY TEST DETAIL SECTION

NYE SRC No.014

30-045-11663-00-00 J-13-30N-11W

----

Active Gas (Producing)

Test Date: 6/26/2008 Permitted Injection PSI:

Actual PSI:

Test Reason:

Test Result:

Annual IMIT

Repair Due:

9/29/2008

Test Type:

Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Unable to blow down. BH 5 min shut - in = 72

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, enforcement action will occur. Such enforcement may include this office issuing a NOTICE OF VIOLATION with a penalty and/or applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well for your violation of OCD rules.

Sincerely,

Note: Bradenhead Tests are performed every 3 years. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.