

RECEIVED

T 32/R10/S32

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

JUN 09 2008

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an Abandoned well. Use Form 3160-3 (APD) for such proposals.

5 Lease Serial No NMNM99357 State

6 If Indian, Allottee or tribe Name

7 If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
 Oil Well Gas Well Other

8. Well Name and No
Martinez GU J #IN MV/DK

2. Name of Operator
BP AMERICA PRODUCTION COMPANY

9. API Well NO
3004533815

3a. Address
**521 S. Boston Ave., Tulsa, OK 74103
Room S1008A**

3b. Phone No (include area code)
918-925-6587

10. Field and Pool, or Exploratory Area
Blanco Mesaverde/Basin Dakota

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SW/NW Sec 32 T32N R10W

11 County or Parish, State
SAN JUAN, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Water shut-Off
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Other
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	
			<input type="checkbox"/> Reclamation
			<input type="checkbox"/> Recomplete
			<input type="checkbox"/> Water Disposal

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

re
Subject well first delivered December 12, 2007
Production estimated at 100 MCDF, 1 BWPD; and 1 BOPD
Basin Dakota formation reported as C01 as of December 1, 2007
Blanco Mesaverde formation reported C02 as of December 1, 2007
Gas metered through El Paso meter 86476

ENTERED
AFMSS
JUL 18 2008

BY MJT
RCVD JUL 23 '08

New Well Notice #7

OIL CONS BILL

DIST. 3

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Nicole Fisher

Title **Production Analyst**

Signature *Nicole Fisher*

Date **May 30, 2008**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by _____ Title _____ Date **JUN - 9 2008**

Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office _____ FARMINGTON FIELD OFFICE BY *MJT*

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

~~FARMINGTON~~ *Amoos*