

Bill Richardson

Joanna Prukop
Cabinet Secretary
Reese Fullerton

Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



October 7, 2008

Cherry Hlava B P America PO Box 3092 Houston TX, 77253

Re: Riddle H #4, A-21-30N-09W, API # 30-045-11793

Dear Ms. Hlava:

The 2008 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before January 8, 2009. Bradenhead psi of 288 was reported.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement top; provide gas analysis from both the production and intermediate casing.

Reference: RBDMS CTP0827554741 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Kelly G. Roberts

Deputy Oil & Gas Inspector

District III-Aztec

CC: Well File

