14. I hereby certify that the foregoing is true and correct.
Signed Jamie Goodwin Title Regulatory Technician Date 09/22/2008.
(This space for Federal-or State Office use) APPROVED BY

REVISED

SEE ATTACHED FOR CONDITIONS OF APPROVAL

BLM CONDITIONS OF APPROVAL

Workover and Recompletion Operations:

- 1. A properly functioning BOP and related equipment must be installed prior to commencing workover and/or recompletion operations.
- 2. If this well is in a Seasonal Closure Area, adhere to the closure requirements and timeframes.
- 3. If casing repairs are required, contact this office to obtain prior approval before conducting casing repair operations.

SURFACE USE OPERATIONS:

The following Stipulations will apply to this well unless a particular Surface Managing Agency or private surface owner has supplied to BLM and operator a contradictory environmental stipulation. The failure of operator to comply with these requirements may result in assessments or penalties pursuant to 43 CFR 3163.1 or 3163.2. A copy of these conditions of approval shall be present on location during construction, drilling and reclamation activity.

An agreement between operator and fee landowner will take precedence over BLM surface stipulations unless (in reference to 43 CFR Part 3160) 1) BLM determines that operator's actions will affect adjacent Federal or Indian surface, or 2) operator does not maintain well area and lease premises in a workmanlike manner with due regard for safety, conservation and appearance, or 3) no such agreement exists, or 4) in the event of well abandonment, minimal Federal restoration requirements will be required.

STANDARD STIPULATIONS: All surface areas disturbed during work-over activities and not in use for production activities will be reseeded. This should occur in the first 90 days after completion of work-over activities.

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the work-over or recompletion activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.