UNITED STATES DEPARTMENT OF THE INTERIOR

Sundry Notices	and Reports on Wells
	5. Lease Number
Type of Well	SF-078417 6. If Indian, All. or
GAS	SEP 1 7 2007 Tribe Name
	Management 7. Unit Agreement Name
Name of Operator	Famington Field Office San Juan 28-7 Uni
ConocoPhillips	8. Well Name & Number
Address & Phone No. of Operator	#194F
PO Box 4289, Farmington, NM 874	9. API Well No.
	30-039-30200
Location of Well, Footage, Sec., 1015'FNL & 1495'FEL	T, R, M 10. Field and Pool
Sec. 21, T28N, R7W, Unit Letter B	B (NWNE) Blanco MV / Basin DK
	11. County and State Rio Arriba NM
	Recompletion New Construction Plugging Back Non-Routine Fracturing
Final Abandonment X_ B. Describe Proposed or Completed As discussed with A.O. Bill Leiss, facil 2) in order to avoid a pipeline which is	Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection Other
Final Abandonment X_ B. Describe Proposed or Completed As discussed with A.O. Bill Leiss, facil 2) in order to avoid a pipeline which is	Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection Other Operations Ities will need to be set at the southeast corner of the well pad (corn located near the center of the location. As a result of placing the construction zone behind the equipment cannot be re-contoured back
Final Abandonment X B. Describe Proposed or Completed As discussed with A.O. Bill Leiss, facil 2) in order to avoid a pipeline which is facilities in the southeast corner, the c	Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection Other Operations Ities will need to be set at the southeast corner of the well pad (corn located near the center of the location. As a result of placing the construction zone behind the equipment cannot be re-contoured back
Final Abandonment X B. Describe Proposed or Completed As discussed with A.O. Bill Leiss, facil 2) in order to avoid a pipeline which is facilities in the southeast corner, the c	Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection Other Operations Ities will need to be set at the southeast corner of the well pad (corn located near the center of the location. As a result of placing the construction zone behind the equipment cannot be re-contoured back: 1 slope shall be attained.
Final Abandonment X B. Describe Proposed or Completed As discussed with A.O. Bill Leiss, facil 2) in order to avoid a pipeline which is facilities in the southeast corner, the c	Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection Other Operations Ities will need to be set at the southeast corner of the well pad (corn located near the center of the location. As a result of placing the construction zone behind the equipment cannot be re-contoured back: 1 slope shall be attained. RCUD OCT 22'08