

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
XTO ENERGY INC

3a. Address
382 CR 3100 AZTEC, NM 87410

3b. Phone No. (include area code)
505-333-3100

4. Location of Well (Footage, Sec, T, R, M, or Survey Description)
1735' FNL & 1530' FEL SWNE Sec. 33 (G) - T30N-R10W N.M.P.M.

5. Lease Serial No.

NMSE - 078204A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No.

BASSETT #2

9. API Well No

30-045-09074

10. Field and Pool, or Exploratory Area

AZTEC PICTURED CLIFFS

11. County or Parish, State

SAN JUAN NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- | | | | |
|---|--|--|---|
| <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input type="checkbox"/> Other |
| <input type="checkbox"/> Change Plans | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. plugged and abandoned this well per the attached report 7/6/09

RCVD JUL 16 '09

OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

BARBARA J CONDER

Title REGULATORY CLERK

Signature

Barbara J Conder

Date 07/10/09

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

JUL 14 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

B 7/22

EXECUTIVE SUMMARY REPORT

1/1/2009 - 7/10/2009
Report run on 7/10/2009 at 2:33 PM

Bassett 02

7/1/2009	Anchors tstd 6/09. MIRU A-Plus Rig #6. SITP 0 psig. SICP 150 psig. SIBHP 0 psig. Bd well. ND WH. NU BOP. TOH w/2 - 2-1/16" IJ tbgs (6' & 8'), 74 jts 2-1/16" IJ tbgs, SN & 2-1/16" x 9' MA. MIRU WLU. RIH w/2.80" GR to 2,510'. POH w/GR. RIH w/3-1/2" CIBP & set @ 2,494'. TIH w/2-1/16" tbgs. Tgd CIBP @ 2,494'. Circ w/20 BFW. Circ & cln w/22 BFW. Attd PT csg to 800 psig. Press dropd fr/800 to 600 psig in 1". Rltd press. Plug #1 w/24 sxs Class B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx, 28.32 cuft). Ppd dwn tbgs w/4.82 bbls cmt. Cmt fr/2,494' to 1,914'. TOH w/tbgs. Rpr planned P&A operations for 7/1/09 to Kelly Roberts w/NMOCD & BLM cmt ln 6/30/09. No reg rep on loc to witness operations. SDFN.
7/2/2009	SITP 0 psig. SICP 0 psig. SIBHP 0 psig. RIH w/GR & tgd TOC @ 1,930'. POH w/GR. PT csg to 800 psig w/4 BFW for 5". Tstd OK. Rltd press. Perfd 3 sqz holes @ 1,487' w/3-1/8" csg gun. POH w/csg gun. Attd to EIR. Press to 800 psig. Could not EIR. Rpt to Steve Mason w/BLM & Kelly Roberts w/NMOCD of results. Joe Rublid w/BLM on loc to approve operations. TIH w/tbgs & tgd TOC @ 1,945'. Attd EIR. Press to 800 psig. Could not EIR. BLM chngd Kirtland top to 1,387'. Perfd 3 sqz holes @ 1,437' w/3-1/8" csg gun. POH w/csg gun. Attd to EIR. Press to 800 psig. Could not EIR. BLM approved perfs @ 1,332'. Perfd 3 sqz holes @ 1,332' w/3-1/8" csg gun. POH w/csg gun. EIR @ 1.0 BPM & 500 psig. Estb circ fr/BH vlv. TIH w/47 jts 2-1/16" tbgs. EOT @ 1,550'. Plug #2 w/10 sxs cmt (mixed @ 125.6 ppg, 1.18 cu ft/sx yield, 11.80 cu/ft). Ppd dwn tbgs w/2.01 bbls cmt. Cmt fr/1,550' to 1,332'. TOH w/tbgs. Estb circ fr/BH vlv. Plug #2A w/35 sxs Class B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx, 41.30 cu/ft). Ppd dwn csg w/7.04 bbls cmt. Displcd w/9.5 BFW. Full circ fr/BH vlv thru cmt pmp operations. SWI. SDFHWE. Joe Rublid w/BLM on loc & witnessed operations.
7/6/2009	SICP 0 psig. SIBHP 0 psig. RIH w/GR. Tgd TOC @ 1,065'. POH w/GR. Perfd 3 sqz holes @ 152' w/3-1/8" csg gun. POH w/csg gun. EIR & circ fr/BH vlv w/2 BFW. Plug # 3 w/57 sxs Class B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx, 67.26 cu/ft). Ppd dwn csg w/11.46 bbls cmt. Circ w/3 bbls gd cmt fr/BH vlv. ND BOP. RDMO A-Plus Rig #6. Dug out WH. Cut off csg. Instl DHM w/25 sxs Class B cmt. Cln loc. P&A operations complete. Operations suspended for remediation. Joe Rublid w/BLM on loc & witnessed operations.
