RECEIVED

Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR

AUG 2 0 200909

FORM APPROVED

Budget Bureau No 1004-0135

AUS 2 0 2009

Date:

(June 1990) BUREAU OF L	AND MANAGEMENAureau of Land Manager =	Expires March 31, 1993
	Farmington Field Office	Expires March 31, 1993 Lease Designation and Serial No
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir Use "APPLICATION FOR PERMIT -" for such proposals		SF - 078977
		6 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		RCVD AUG 21 '09
Type of Well		7. If Unit or CA, Agreement Designation
Oil Well S Cas Well	Other	OIL CONS. DIV.
☐ Oil Well ☐ Gas Well	Other	8 Well Name and No
2. Name of Operator		DIST. 3
Synergy Operating, LLC ((163458) OGRID # 163458	Madrid 29-13-6 # 111
		9 API Well No
3. Address and Telephone No	. (505) 005 5540	00.045.00400
PO Box 5513	(505) 325-5549	30-045-33469
Farmington, NM 87499		10 Field and Pool, or Exploratory
4. Location of Well (Footage, Sec, T. R, M, or Survey Description) Basin Fruitland Coal		
Unit B, 900' FNL, 1640' FEL, Sec 06, T29N - R13W		11. County or Parish, State
		San Juan County
		New Mexico
12. CHECK APPROPRIATE BOX(S)	TO INDICATE NATURE OF NOTICE, REPORT, OR	
TYPE OF SUBMISSION TYPE OF ACTION		
5 7		1 or 184
Notice of Intent	Abandoment Recompletion	Change of Plans New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Converion to Injection
	Other -	Dispose Water
		(Note Report results of multiple completion on Well
Completion or recompletion Report and Log Form) 13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including, estimated date of starting work		
If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones of pertinent to this work.		
SYNERGY OPERATING, LLC PLANS TO IMMEDIATELY MOVE A WORKOVER RIG ON THE SUBJECT WELL TO RESTORE PRODUCTION. THE SUBJECT WELL HAS A DOWNHOLE ROD PUMP THAT IS NOT OPERATING PROPERLY.		
TRODUCTION. THE SUBJECT WELL HAS A DOWNINGE ROD FORM THAT IS NOT OF EXAMING FROM ERET.		
SYNERGY BELIEVES THAT THERE MAY BE COAL FINES OR DEBRIS THAT ARE NEGATIVELY AFFECTING PUMPING OPERATIONS		
NATURAL GAS PRODUCTION AND ASSOCIATED PRODUCED WATER PRODUCTION HAVE BEEN NEGATIVELY IMPACTED.		
SANIEDON DEODOSES TO MONE A DIC AND AND AND BACKAGE WITH A CLOSED LOOP ELOWDACK TANK SASTEM TO		
SYNERGY PROPOSES TO MOVE A RIG AND AND AIR PACKAGE WITH A CLOSED-LOOP FLOWBACK TANK SYSTEM TO CLEANOUT THE SUBJECT WELL AND CIRCULATE ANY DEBRIS FROM THE WELL WHICH HAS BEEN NEGATIVELY AFFECTING		
THE PRODUCTION.	TOOLYTE AIN BEDITO FROM THE WELL WINOT	TINO BEEN NEON THEE THE ESTATE
	D TO TAKE TWO TO THREE DAYS TO COMPLETE	
THIS WELL TO SYNERGY'S OPERATIONS, SYNERGY ANTICIPATED COMMENCING ACTIVITY ON MONDAY, AUGUST 24TH, 2009.		
THERE WILL BE NO NEW SURFACE DISTURBANCE ON THIS SHORT OPERATION. THE C-144CLEZ FORM HAS BEEN FILED		
WITH THE NMOCD FOR THIS PROJECT.	_	
14. I hereby certify that the forestoing is to	pute and correct	
Signed:	Title: Engineering Mana	nger Date. 08-20-2009
Thomas E. Mullins		Telephone: (505) 599-4905

Title 18 U S C Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction

This space for federal or state office use

Conditions of approval if any

Approved by. Original Signed: Stephen Mason



Title'_