	State of New Mexico	Form C-103
to Appropriate	Energy, Minerals and Natural Resources Department	Revised 1-1-89
District Office		
	OH CONCERNATION DIVICION	
District I	OIL CONSERVATION DIVISION	Well API No.
P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St.	30-045-31076
District II	Santa Fe, NM 87505	5. Indicate Type of Lease
P.O.Box Drawer DD, Artesia, NM 882	210 CT pana	STATE FEE X
District III		6 State Oil & Gas LeaseNo.
1000 Rio Brazos Rd., Aztec, NM 874		
SUNI	DRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE	E THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR	7. Lease Name or Unit Agreement Name
PLUG BACK TO	O A DIFFERENT RESERVOIR, USE "APPLICATION FOR REPMIT"	
	(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:		Northeast Blanco Unit
Oil Well Gas Well	Other	
2. Name of Operator Devon	Energy Production Co. L.P.	8. Well No. 65A
3. Address of Operator 1751 High	nway 511 Navajo Dam, New Mexico 87419 Attn: Kenny Rhoades	9. Pool name or Wildcat
4. Well Location		Basin Dakota / Blanco Mesa Verde
Unit LetterP_:865'	Feet From The South Line and 1120' Feet From The East	Line
Section 11	Township 31N Range 7W NMPM	County San Juan
	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6452' GL	
11.	Check Appropriate Box to Indicate Nature of Notice, Report, or	Other Data
NOTICE OF IN	TENTION TO: SUBSEQUENT	REPORT OF:
Г	BLUC & ADANDON DEMEDIAL WORK	ALTERNIC CAGNIC
PERFORM REMEDIAL WORK	PLUG & ABANDON	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS.	PLUG & ABANDON
<u>-</u>		PLUG & ABANDON
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS.	
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB	PLUG & ABANDON
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB	PLUG & ABANDON
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle	PLUG & ABANDON
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle	PLUG & ABANDON
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103.	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle	PLUG & ABANDON
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a	PLUG & ABANDON
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retries	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle	PLUG & ABANDON X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retries	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2	PLUG & ABANDON X ny proposed ed Dakota/.Mesa Verde -3/8" production
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2	PLUG & ABANDON X ny proposed ed Dakota/.Mesa Verde -3/8" production
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2	PLUG & ABANDON X ny proposed ed Dakota/.Mesa Verde -3/8" production
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2	PLUG & ABANDON X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2	PLUG & ABANDON X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and Dakota/Mesa Verde.	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle croduction packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2 d landed at 7947'. The well was then turned to sales as a downhole commingle to the sales as a downhole commingle to	PLUG & ABANDON X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and Dakota/Mesa Verde.	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle croduction packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2 d landed at 7947'. The well was then turned to sales as a downhole commingle to the sales as a downhole commingle to	PLUG & ABANDON X ny proposed ed Dakota/.Mesa Verde -3/8" production
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle croduction packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2 d landed at 7947'. The well was then turned to sales as a downhole commingle to the sales as a downhole commingle to	PLUG & ABANDON X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and Dakota/Mesa Verde.	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle croduction packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2 d landed at 7947'. The well was then turned to sales as a downhole commingle to the sales as a downhole commingle to	PLUG & ABANDON X ny proposed ed Dakota/.Mesa Verde -3/8" production
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and Dakota/Mesa Verde.	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle croduction packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2 d landed at 7947'. The well was then turned to sales as a downhole commingle to the sales as a downhole commingle to	PLUG & ABANDON X ny proposed ed Dakota/.Mesa Verde -3/8" production
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and Dakota/Mesa Verde.	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2d landed at 7947'. The well was then turned to sales as a downhole commingle even by the sales as a downhole comming to the sales as a	PLUG & ABANDON X
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operat work) See Rule 1103. Work commenced to remove p Service rig moved in and retrie tubing was then run in well and Dakota/Mesa Verde.	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2d landed at 7947'. The well was then turned to sales as a downhole commingle even by the sales as a downhole comming to the sales as a	PLUG & ABANDON X ny proposed ed Dakota/.Mesa Verde -3/8" production
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) See Rule 1103. Work commenced to remove preservice rig moved in and retriestubing was then run in well and Dakota/Mesa Verde. 1 herby certify that the information about the commence of	CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST & CEMENT JOB OTHER Downhole Commingle tions (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting a production packer from wellbore and produce as a downhole commingle eved packer from well. Well was then cleaned to PBTD at 8040'. The 2d landed at 7947'. The well was then turned to sales as a downhole commingle even by the sales as a downhole comming to the sales as a	PLUG & ABANDON X

DEPUTY OIL & GAS INSPECTOR, DIST. SE DATE OF 16 2003

(This space for State Use)